PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3276 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 24.05.21 61 Date: F.R SI NO# Ref.No: Mym-61 Mchanic Name:Md Forhad Mia Engineer Name: Md Jahid Hasan Zone Name: Mymensingh Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 1715769020 Mobile No: **Customer Name: Bissojit Kumar Datt** M/S Jerin Motors **Dealer Name:** Muktagacha, Mymensingh Address: 4927 MD6M14CLXK4P00124 Present Km CH NO Full # **Customer Complain:-TVS King Duramax EN NO Full #** OL4PK4600449 Steering coloum lose Model # Sale Date # 10.02.21 1st PS Kms 1St PS Date Date of Comp# 23.05.21 N/A N/A Date of Repair# Pending Free service information **3rd Free Service** 2nd Free Service **1St Free Service KMs Date KMs** Date **KMs** Date 23.04.21 3,287 939 07.03.21 Observation:-By Mechanic we checked and find that the steering coloum lose. Action Taken:- Please to be replace the steering coloum with steerint coloum cone kit top & bottom by new one under warranty. **Failure Particular** Vendor code Approved Rejected Part Name Qty Part NO. SL 1 Steering coloum 1 G2150010 Steering coloum cone 1 G5320510 kit top Steering coloum cone kit bottom 1 G5320500 3 4 For Head Office Use **Failure Parts Photo** DMS Engineer **Head of Service**