PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD Head Office

DMS JOB NO 2833

		IFAD TOWER	07 Teic	iaon I/A. D	haka-120	٧.,				
		IFAD TOWER	,0, 10,5	F.R SI NO#	240		Date:	22.09.2020		
	Sep-240			Engineer Name:		Md.Pabel Sarker				
Zone Name:	Cumilla			3 4 2 3 12						
Approved by:	Prabir Bisw	as, GM -Head of S	Service & S	pare Parts.						
					Mobile No:		01811993978			
ustomar Name:	Sohag Miah			Dealer Nan	GENERAL SECTION	Adunik Motors				
ddress:	Choddgram	Cumilia			1	10.	Present Kms#	2,050		
Clistomar Collipiani, Cities I				MD6M14CA0K4L00426		241	A. Care	Tvs King Delux lpg		
ear shock absorber has right oil leakage and nose.		EN NO Full #	AK4LK4309555 15.07.2020 17.09.2020			- 4	Model#			
		Sale Date #				24	1St PS Date	1st PS Kms		
		Date of Comp#					13(1)			
		Date of Repair #				atio	1			
		Free service information 3rd Free Service 3rd Free Service								
			1St Free Service		ree Service			KMs		
	Date	KMs	Date KMs	1 1 3 K2 8	Date					
		15.08.2020	1100	Las bac right						

Obserbation:- we checked &found that Rear Shock Absorber has right oil leakage

Action Taken:- Require to replace this parts under warranty for approval.

Failure Particular								
C1	Part NO	Part Name	Qty	Vendor code	Approved	Rejected		
SL		Rear Shock Absorber	01	Gabrial				
1	G2090100	Real Shock Account	<u> </u>					
2				1.1				
3								
4	^ *		0 %					
5				**************************************				
6			***************************************	La transfer				

Failure Parts Photo

For Head Office Use