## TVS PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 23435 Head Office IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO# Date: 20.12.2020 335 Ret.No. Habiganj/Dce/335 Engineer Name: Md. Abduliah Al-Michaeli, Name: Md Shipon Alam Zone Name: Habiganj Zone Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Customer Name: Md. Manik Miah Mobile No: 01740464768 Dealer Mame: Shahjalal Automobile Cunarugat, Habiganj MD6M14CA8J4A06936, CH NO Full # Present Kn 10840 Customer Complain: Ivs King Deluxe Front Shock absorber has been broken. EN NO Full # AK4AJ4113727 Model # CNG/LPG 08.07.2020 Sale Date # Date of Comp# 19.12.2020 15t PS Date | 1st P5 Kms Date of Repair# 19.12.2020 Free service information 3rd Free Service 1St Free Service 2nd Free Service Date KMs Date 05.08.2020 860 12.10.202 Date Observation:- We checked & found that front Shock absorber has been broken Action Taken: New one front shock absorber replaced. Failure Particular Vendor code | Approved | Rejected Qty Part Name Part NO. 62 10 0010 Front shock absorber 3711 04 07 18

Failure Parts Photo

3

m36485

Head of Service

21/2/2020.

Engineer

For Head Office Use

ons complete

OMS

Mohammad Abdullah Al Zahed Senior Service Engineer IFAD MOTORS LTD. Cell: 01701-227974

7