TITE				The second secon	7.		· \$	
	PRODU	JCT PERFOR	RMAN	CEFEE	DBACI	KREP	ORT	154/8
		IFAD MOTORS LTD						
tarner .		The state of the s						DMS NO:
IFAD Towe		Head Office r, Plot-7(New), Tejgoan Industrial						3261
Ref.No	o: Cox's Bazar /April/2	25/04 / (New),	rejgo	an Indus	trial Are	ea, Dha	ka-1208	
Zone Name	Cox's Bazar, Sada	/ - /		F.R SI NO	O#	04	Date:	25.04.2021
Approved by: Prabir Biswas (Head		of Service, Spare Parts & Production)		Name:Kanchan das		Mchanic Na	Mchanic Name: Al-amin	
The second secon		or service, spare Pa	arts & I	Production)		70		
ustomer Name:	Abdur rahim				1			
ddress:	Cox's Bazar ,sadar	ox's Bazar ,sadar				Mobile No: 01888497325		
ustomer Compla	in:-	Dealer Name:				Name:	Sha Motors	
ront shock absorber oil leakage .		EN NO Full #	MD6M14CA0J4D02646 Ak4DJ4316380				Present Kms 850 V	
		Sale Date #	1	74310380	12/4/2021			Tvs King Delu
		Date of Comp#	14.04	.2021 ,		2/4/2021		lpg
		Date of Repair#					1St PS Date	1st PS Kms
		Free service information					No	
		Date	KMs		Free Serv	ice	3rc	Free Service
	hecked & found that F			* Date	K K	Ms	Date	KMs
		Faile	ire Par	ticular				
	Part NO. 52100010	Part Name	Part Name Oty			ode	^	1
GATO	03100	Front Shock Abso	orber	1	1.07401.0	Joue	Approved	Rejected
Failure P	Orte Dhot	,						
Failure Parts Photo		For Head Office Use						
		Head of Service			Engineer			DANS
		For the order						DMS
								,
								5
								Jan 1
								St. B.
					1052			Chr. S
					1 9	KI		1100
								Wixa
The same of the sa		The second section of the second section is a second section of the second section of the second section secti						