PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** 3034 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO 21.01.2021 20 Date: Ref.No: Dhaka/Jan/20 Engineer Name: Milon Hossair Mchanic Name: Md.Yousuf Zone Name: Dhaka 1 Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01956672387 Mobile No: Sweety Begum **Customer Name: Mayer Dowa** Rampura, Dhaka Dealer Name: Address: MD6M14CA0J4L09514 Present Km 4,098 CH NO Full # **Customer Complain:-**AK4LJ4994176 Oil leakege from Rear LH shock absorber EN NO Full # Model # **TVS King Deluxe** Sale Date # 31.10.2020 19.01.2021 Date of Comp# 1St PS Date 1st PS Kms Date of Repair# Free service information **1St Free Service** 2nd Free Service **3rd Free Service** KMs Date KMs Date Date **KMs** 27.11.2020 965 04.01.21 Obserbation:- We checked & found that oil leakege Rear LH shock absorber. The Million Hossail And Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular Vendor code Part NO. Part Name Approved Rejected SL G2090100 **SHOCK ABSORBER** Gabrial 1 a facility **ASSY REAR** 2 3 4 service informatio For Head Office Use **Failure Parts Photo Head of Service** KiviEngineer **DMS** Mind and lete

Note: Miles to the second seco

Will opposite the