PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: MOTORSUMITED **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO# 12.12.2020 244 Date: Ref.No: Dec-244 Engineer Name: Md.Pabel Sarker Mchanic Name: Sumon Dali Zone Name: Cumilla Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01856101079 Mobile No: **Customer Name:** Younos Dealer Name: **Adunik Motors** Address: Burora, Cumilla MD6M14CA8K4L00111 Present Km 7231 **Customer Complain:-**CH NO Full # **TVS King Deluxe** EN NO Full # AK4LK4806106 Rear shock absorber has right oil Model # leakage and nose. noise . Sale Date # 05.07.2020 Date of Comp# 12.12.2020 1St PS Date 1st PS Kms Date of Repair# Free service information 2nd Free Service **3rd Free Service 1St Free Service KMs KMs KMs Date** Date Date 05.08.2020 941 06.10.2020 4,321 12.12.2020 7231 Observation:we checked &found that Rear Shock Absorber has right oil leakage. Action Taken:- Require to replace this parts under warranty for approval Failure Particular

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G2090100	Rear Shock Absorber	01			
2			A	A Anna Anna	No.	
- 3						
4				300000	100 mg 10	

Failure Parts Photo	For Head Office Use			
· 4.	Head of Service	Engineer	DMS	
	mswas 14/12020	2.2020	Handale, Sole, Sale,	

Drys Complete