## PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Dhaka/May/24 F.R SI NO# Date: 16.05.2021 Engineer Name: Milon Hossain Zone Name: Dhaka 1 Mchanic Name: Md.Yousuf Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) **Customer Name: Guljar Hossain** Mobile No: 01782-370721 Address: Sirajdikhan , Munshiganj Dealer Name: Mayer Dowa TVS Center Customer Complain:-CH NO Full # MD6M14CA6J4L09369 Present Kms 4087 Front Shockabsorber Oil Leakage EN NO Full # AK4LJ4092280 Model# TVS King Deluxe Sale Date # 23.01.2021 Date of Comp# 06.05.2021 1St PS Date 1st PS Kms Date of Repair# Free service information 2nd Free Service 1St Free Service 3rd Free Service Date **KMs** Date **KMs** Date **KMs** 20.02.201 1120 25,03.2021 2,890 Observation:we checked &found that front Shockabsorber oil Leakage . Action Taken:- Require to replace this parts under warranty for your kind approval. Failure Particular SL Part NO. Part Name Qty Vendor code Approved Rejected 1 G4100180 SHOCK ABSORBER FRONT 2

Failure Parts Photo	For Head Office Use		
	Head of Service	Engineer	DMS
	2005/2021	2205/202	on John La

3 4 5