PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3348 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 12.08.2021 F.R SI N 308 Date: Ref.No: Sylhet/Aug/12/308 Mchanic Name: Delower Hosain Engineer Name: Tisu Barua Zone Name: Sylhet Sadar Approved by: Koushik Sarkar (COO) 01732981548 Mobile No: Customer Name: | Md. Abdul Mothin M/S Shahporan Motors Dealer Name: Jogonnathpur, Sylhet. Address: MD6M14CL7K4P00081 Present Km 15,965 CH NO Full # **Customer Complain:-**0L4PK4300379 EN NO Full # Oil leakege from rear shock absorber **TVS King Duramax** Model# 04.02.2021 Sale Date # 1St PS Date 1st PS Kms 29.07.2021 Date of Comp# Date of Repair# Free service information **3rd Free Service** 2nd Free Service **1St Free Service KMs** Date Date KMs Date **KMs** 7659 15.05.2021 1130 07.04.21 3,659 29.02.2021 Obserbation:- We checked & found that oil leakege rear shock absorber. Action Taken:- Require to replace this parts under warranty for your approval, Failure Particular Approved Rejected Xendor code Qty Part Name SL Part NO. SHOCK ABSORBER ASSY 01 1 G2090100 2 3 4 For Head Office Use Failure Parts Photo **DMS** Engineer **Head of Service** Complete.

DM5