PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Mym-27 F.R SI NO 27 Date: 31.12.20 Zone Name: Mymensingh Engineer Name:Md Jahid Hasa Mchanic Name:Utpal Chiran Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) **Customer Name: Msud Rana** Mobile No: 01727762060 Address: Cecuya, Mymensingh Dealer Name: **Jerin Motors** Customer Complain:-CH NO Full # MD6M14CL2K4P00182 Present Km 5884 Steering coloum lose every week EN NO Full # OL4PK4500485 **TVS King Duramax** Model# Sale Date # 28.10.20 Date of Comp# 17.12.20 1St PS Date 1st PS Kms Date of Repair# **Pending** N/A N/A Free service information 1St Free Service 2nd Free Service **3rd Free Service** Date **KMs Date KMs** Date **KMs** 28.11.20 1204 30.12.20 5,884 Observation: we checked and found that the sreering coloum Jam nut lose & Steering column thread are damage. Action Taken:- Please to be replace the steering column by new one under warranty.

Failure Particular								
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected		
1	G2150010	Steering column	1					
2								
3								
4								
						_		

<u>Failure Parts Photo</u>	For Head Office Use				
	Head of Service	Engineer	DMS		
	Colleged of chapter		John Start		