TVS	DDODLI						
	PRODU	CT PERFORI	MAN	CE FEEDE	BACK REP	ORT	
FAD		IFAD MOTORS LTD					DMS NO:
MOTORS LIMITED		Н	Head Office				
	IFAD Tower,				ial Area. Dha	ka-1208	3195
Ref.No:			-16-	F.R SI NO#	35	T	23.02.21
		Account to the second s		Engineer Name:	:Md Jahid Hasan		e:Md Forhad Mia
		ad of Service Snar	e Parts				
	i radii Distras (ric	au or service, spar	C T di ts	& 1 Toddetto	''/		
mer Name:	Md Forhad			Mobile No:		01740845815	
		ngh ′		Dealer Name:	Jerin Motors		
Customer Complain:-				127	Present Km	ys # 6945	
Steering coloum lose		EN NO Full #	N NO Full # OL4PK4800423			TVS King Duramax	
		Sale Date #	# 27.10.2020			iviodei #	
* * * * * * * * * * * * * * * * * * *		Date of Comp# 20.02.2021			1St PS Date	1st PS Kms	
		Date of Repair#				N/A	N/A
		Free service information					4.0
		1St Free Service		2nd Free Service		3rd Free Service	
		Date	KMs	Date	KMs	Date	KMs
				/	2,876	24.01.21	5098
vation:- We	checked and found	that the steering	coloun	n lose .	,		
Taken:- Plea	se to be replace t	he steering coloun	n with:	steering colou	ım eone kit top	& bottom b	v new one under
nty.				/	/		,
	,	Fa	ilure Pa	articular			
SL Part NO.		Part Name		Oty	Vendor code	Approved	Rejected
1 G2150010				1		прриотеа	Rejected
			cone				y ⁶
G5320510		kit top					-
		Steering coloum	cone				
G5320500				(1 /			1
Y	**************************************	-			L. Control of the Con	<u> </u>	
Failure Pa	For Head Office Use						
Tanarera	113111010			For F	lead Office Use		,
ranarera		Head o	of Servi		lead Office Use Engine	eer	DMS
	Zone Name: pproved by: mer Name: ss: mer Complai ng coloum lo Taken:- Plea nty. P G2150010 G5320510	Ref.No: Mym-35 Zone Name: Mymensingh Approved by: Prabir Biswas (Hemer Name: Md Forhad ss: cecuya, Mymensing mer Complain:- ng coloum lose vation:- We checked and found a Taken:- Please to be replace to the theory. Part NO. G2150010 G5320510	IFAD Tower, Plot-7(New), Ref.No: Mym-35 Zone Name: Mymensingh Ipproved by: Prabir Biswas (Head of Service, Sparent Mer Name: Md Forhad SS: cecuya, Mymensingh Improved By: Prabir Biswas (Head of Service, Sparent Mer Name: Md Forhad SS: cecuya, Mymensingh In Taken:- Please to be replace the steering colour Inty. In Taken:- Please to be replace the steering colour Inty. Fart No. Part Name G2150010 Steering colour Inty Into Into Into Into Into Into Into Into	Ref.No: Mym-35 Zone Name: Mymensingh Approved by: Prabir Biswas (Head of Service, Spare Parts of Mer Name: Md Forhad ss: cecuya, Mymensingh Mer Complain:- CH NO Full # OL4PK Sale Date # 27.10. Date of Comp# 20.02. Date of Repair# 1St Free Service Date KMs 21.11.20 1079 vation:- We checked and found that the steering coloum with sinty. Failure Properties of Steering coloum cone kit top Steering coloum cone	IFAD Tower, Plot-7(New), Tejgoan Industr Ref.No: Mym-35 F.R SI NO# Zone Name: Mymensingh Engineer Name: Approved by: Prabir Biswas (Head of Service, Spare Parts & Production of Service, Spare Pa	IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dha Ref.No: Mym-35 F.R SI NO# 35 Zone Name: Mymensingh Engineer Name: Md Jahid Hasan Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) mer Name: Md Forhad Mobile No: Ss: cecuya, Mymensingh Dealer Name: mer Complain:- Ing coloum lose EN NO Full # MD6M14CL5K4P00127 Date of Comp# 20.02.2021 Date of Repair# Free service informati 1St Free Service 2nd Free Service Date KMs Date KMs 21.11.20 1079 26.12.20 2,876 vation:- We checked and found that the steering coloum lose . I Taken:- Please to be replace the steering coloum with steering coloum cone kit top inty. Failure Particular Part NO. Part Name Qty Vendor code G2150010 Steering coloum cone kit top Kit top Steering coloum cone kit top Steering coloum cone	IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Mym-35 F.R SI NO# 35 Date: Zone Name: Mymensingh Engineer Name: Md Jahid Hasan Mchanic Name Mobile No: O17408458 See: Cecuya, Mymensingh Dealer Name: Dealer Name: O17408458 See: Cecuya, Mymensingh Dealer Name: O17408458 See: Date Comp# O14PK4800423 Model # O14PK4800423 Model # O14PK4800423 Sale Date # 27.10.2020 Date of Repair# N/A