

failure1: sensor reconstruction from first-order + external-wrench replay

gyro RMSE [0.042 0.0809 0.0288]

specific-force RMSE [1.0032 0.1607 0.3713]

