

June 8, 2026

MR. MICHAL NLINKA

Dubai, United Arab Emirates

Subject: Technical Inspection Findings – Lamborghini Urus VIN# ZPBEA1ZL3MLA15451

Dear Mr. Michal,

The above-mentioned vehicle was received at MANSORY ASC Auto General Repairing LLC on **25 May 2026** with an odometer reading of **61,596 km** due to an abnormal engine-related noise.

During the initial inspection, a worn exhaust bracket was identified and replaced. As the noise persisted, further diagnostics were carried out, confirming that the source of the noise originated from the engine.

Following your written authorization for engine disassembly and inspection, the engine was dismantled. Internal inspection revealed damage to the **crankshaft bearings and connecting rod bearings**, requiring replacement together with all associated components necessary to restore proper engine operation and reliability.

Technical Findings

Based on the condition of the damaged components, the observed wear is consistent with progressive internal engine deterioration that develops over an extended period of operation.

The vehicle was previously received by MANSORY on **28 March 2024** with an odometer reading of **36,429 km** and was later received on **25 May 2026** with an odometer reading of **61,596 km**, representing approximately **25,167 km** of operation between visits.

The damage identified during the teardown could only be confirmed through internal engine inspection. Mechanical wear of this nature may not be detectable through routine visual inspections or electronic diagnostic scans, as such damage does not necessarily generate fault codes or warning messages.


MANSORY has no records of the vehicle's maintenance history, repairs, operating conditions, or modifications performed outside our facility during the period between the above visits. Accordingly, we are unable to determine the exact time, cause, or circumstances under which the damage originated.



Based on our findings, the damage was present prior to engine disassembly and was confirmed only after the authorized internal inspection was performed.


This statement is issued solely to document the findings observed during our inspection and repair process.

Yours faithfully,


NEERAJ RAJEEV
SERVICE ADVISOR


ELIE HAJJ
WORKSHOP MANAGER


AHMAD ABBADI
OPERATIONS MANAGER


MOHAMMAD AL SAHEB
MANAGING DIRECTOR

