
Machine: masses, lever, contacts and release
D_1
D_2
Arrival delay Δt
contact stiffness k
F_R, v_R
Lift and motion
Guided receiver
m_R, h_R, v_R
Support port
Measure preparation and reset