

Date	Invoice #
1/31/2026	186

Bill To
Anthony Bradfield 1000 Uptown Park Blvd #24 Houston, TX 77056

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
	Due on receipt		1/31/2026			
Description			Quantity	Price Each	Amount	
January Honda Jet Flights			0	1,000.00	0.00T	
January Honda Jet Flights			0	-1,000.00	0.00	
1/1/2026 - Houston Exec Airport - Increase is rent - adjustment for January on Fixed Invoice			1	40.00	40.00	
1/2 Houston Exec Airport Inv 26-170139 - Tony San Antonio Trip			1	420.42	420.42	
1/2 Gen Korean BBQ - David - San Antonio trip			1	41.62	41.62	
1/3 Million Air - SAT - Tony San Antonio Trip			1	422.00	422.00	
1/20 Houston Exec Airport Inv 26-171177 - Tony trip to San Antonio			1	427.01	427.01	
1/20 Million Air SAT Inv 146939 - Tony trip to San Antonio			1	453.60	453.60	
1/1 City of Sugarland - Hanger Rent/Monthly - December 2025 - \$720.00 (\$30 Late Fee)			1	360.00	360.00	
1/3 Garmin A-V-Ation Inv 5515854 monthly payment - Account AVUSD1165527 - Total \$59.11			1	29.55	29.55	
1/5 GoGo Galileo Inv 11473032312260105 - Internet N820JL - Hourly Plan \$525, Minutes Overage \$735 (Tony 12/26-12/29) - Total \$1,260			1	997.50	997.50	
1/5 Doordash - Chick-fila - Lunch for Florida Banyan Team - Total Cost \$165.19			1	82.61	82.61	
1/6 Super - Reimburse David - App to help with booking hotels - Total Invoice \$15.00			1	7.50	7.50	
1/6 Petroleum Service Company Order 259400 - Oil for Cirrus - Total Invoice \$101.00			1	50.50	50.50	
1/6 Meguiar's - David - Wipe-off detailer for HondaJet - Total Invoice \$17.94			1	8.96	8.96	
1/6 Aircraft Spruce Order 17820029 - Upholstery Cleaner for HondaJet - Total Invoice \$28.79			1	14.39	14.39	
1/6 Aero Specialties Order 106158 - Upholstery Conditioner for HondaJet - Total Invoice \$74.41			1	37.21	37.21	
1/6 Amazon Inv 0199466 - Leather Cleaner - for HondaJet - Total Invoice \$20.51			1	10.25	10.25	
1/13 Global Select Inv 2600801 - Maintenance - aircraft towing for N199TB - Total Invoice \$54.00			1	27.00	27.00	
1/13 Global Select Inv 2600859 - Maintenance - aircraft towing for N199TB - Total Invoice \$54.00			1	27.00	27.00	
					Total	

Date	Invoice #
1/31/2026	186

Bill To
Anthony Bradfield 1000 Uptown Park Blvd #24 Houston, TX 77056

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
	Due on receipt		1/31/2026			
Description			Quantity	Price Each	Amount	
1/17 Jetdetail Unlimited Inv 002 - Exterior Detail for HondaJet - Total Invoice \$550.00			1	275.00	275.00	
1/20 City of Sugarland - Hanger Rent/Monthly - January 2026 - \$690.00			1	345.00	345.00	
1/21 Travers & Associates Customer ID 108728 - New policy 2019 HondaJet, N820JL Annual Premium \$81,500 3rd of four payments			1	7,033.62	7,033.62	
1/21 Travers & Associates Customer ID 108728 - New policy 2019 Honda Aircraft Co Llc Ha-420 - Total Invoice \$17.00			1	8.50	8.50	
1/26 Houston Aviation Center LLC WO 6953-10-2025 -Annual inspection performed on 11/25 for N199TB - Total Invoice \$8,888.14			1	4,444.08	4,444.08	
1/31 Turbine Aircraft Logistics Inv 2293 - HondaJet Support & Pilot Services - Total Invoice \$425.87			1	212.93	212.93	
1/31 Honda Aircraft Co - Monthly Airframe Cost - Reporting month January - Total Cost \$6,317.35			1	1,705.68	1,705.68	
1/31 Honda Aircraft Co - Monthly Engine Cost - Reporting month January - Total Cost \$3,643.20			1	983.66	983.66	
					Total	\$18,465.59

Organization	Laminar Holdings, LLC
Aircraft	N820JL
Airframe Program	N820JL Airframe P3 2026
Engine Program	N820JL Engine EMC2
Reporting Name	N820JL January 2026
Status	Reported
Reporting Month	January, 2026
Hour Meter Start	1,800
Hour Meter End	1,808.8
Hours Used	8.8
Cycle Meter Start	1,422
Cycle Meter End	1,429
Cycles Used	7
Air-Sync Timestamp	Jan 31, 2026 07:00pm
Month Airframe Cost	\$6,317.35
Month Engine Cost	\$3,643.20
Month Total Cost	\$9,960.55



Richard D. Hodge
 CEO, RJH Structured Holdings

 M 281.846.8212 (text)
 Executive assistant Michelle Caulder
 Contact (m) 281.433.8459 (e) michelle@rjh-llc.com

Tony 27%
Richard 73%

Houston Executive Airport

1900 Cardiff Road
Brookshire, TX 77423
FIN: 20-5253963
281-945-5000

Tony
San Antonio

Invoice: 26-170139
Account #: LAMINAR

1/02/2026
4.27PM

Sold To: Laminar

Ship To: Laminar

Line#	Type	Item/Description	Cr?	Aircraft	Quantity	Units	Unit Price	Extended
1	Fuel	JET A W/ADDITIVE		N820JL	90.00	Gallon	4.6713	\$ 420.42
		Jet A W/Additive		Meter Start: 3122326		Stop: 3122416		
		Delivered: 1/02/2026 - 3:32PM		Truck: JET 4480		Ticket #: 112252		
						Subtotal	\$	420.42
						Total Due	\$	420.42
						Paid-AVCARD Wings	\$	420.42
		AVCARD Wings		Non-Swipe		I Agree to pay the Amount shown to the right	\$ 420.42	
		*****9937		Auth#: 6330WN		in accordance with the Card Issuer agreement.		
		Pmt ID #: 188394						
		C/C Ref #: 042306		Signed: _____				

POSTED

January

Tony

San Antonio



Gen Korean BBQ House

214-396-8746

11745 W Interstate 10, Suite 414

San Antonio, TX 78230

We do NOT take any type of
Digital Payments (Venmo, Paypal, Etc)

Order# 7131857

Station# POS3

Eat In Order

Seat Count=1

Server: Amy M

Table: Table 42

Date: 1/2/25, 11:09 AM

7. Hawaiian Steak	\$0.00
1. Gen Premium Steak	\$0.00
3. Pork Riblets (Spicy)	\$0.00
4. Spicy Pork Bulgogi	\$0.00
41. Deep Fried Mandu	\$0.00
39. Jap Chae	\$0.00
Adult - Dinner	\$31.95

Total Item Count: 7

Subtotal: \$31.95

Total Tax: \$2.64

Total: \$34.59

AMEX 1024 \$34.59

Tip: \$7.03

Total Paid: \$41.62

Suggested Gratuity

%	Tip	Total
25.00% of sale:	\$7.99 =	\$42.58
22.00% of sale:	\$7.03 =	\$41.62
18.00% of sale:	\$5.75 =	\$40.34

Enjoyed your service?

Tag us on Instagram

#gensanantonio

We deliver!

WWW.GENDELIVERS.COM

POSTED

Houston Executive Airport

1900 Cardiff Road
Brookshire, TX 77423
FIN: 20-5253963
281-945-5000

Tony
San Antonio

Invoice: 26-171177
Account #: LAMINAR

1/20/2026
3.42PM

Sold To: Laminar

Ship To: Laminar

Line#	Type	Item/Description	Cr?	Aircraft	Quantity	Units	Unit Price	Extended
1	Fuel	JET A W/ADDITIVE		N820JL	90.00	Gallon	4.7446	\$ 427.01
		Jet A W/Additive		Meter Start: 3145059	Stop: 3145149			
		Delivered: 1/20/2026 - 3:36PM		Truck: JET 4480	Ticket #: 112380			
					Subtotal		\$	427.01
					Total Due		\$	427.01
					Paid-AVCARD Wings		\$	427.01
		AVCARD Wings		Non-Swipe	I Agree to pay the Amount shown to the right	\$	427.01	
		*****9937		Auth#: 9471WN	in accordance with the Card Issuer agreement.			
		Pmt ID #: 189479						
		C/C Ref #: 043015		Signed: _____				

POSTED

Tony
San Antonio



AVFUEL LOCATION

Million Air - SAT
SAT/KSAT
210-828-8181
info.sat@millionair.com
www.millionair.com/sat

01/20/2026

14:40:39

Sale

Receipt No.: 146939
Batch No.: 5596
Terminal ID: 10290018696
Merchant No.: 2935
Entered By: alyssa ramirez

Customer Name:
Card Type: American Express
Card No.: *****1026 Swiped
Exp Date: 12/28
Auth No.: 569386
Tail No.: h820j
Destination:
License/Reg No.:
Delivered On: 01/20/2026

Jet A Fuel with FSII 453.80
Additive
105 US Gallon @ 4.32000 /GAL

Total (USD) 453.60

Customer Signature

X

By signing this receipt, I agree I have received and will pay for the above goods and/or services rendered. Card payments are governed by card issuer agreement.

Thanks A Million!!!
Find Avfuel Worldwide at
www.avfuel.com

POSTED



City of Sugar Land
P.O. Box 5029
Sugar Land, Texas 77487-5029

INVOICE

INVOICE

CUSTOMER	INVOICE DATE	INVOICE NUMBER	AMOUNT PAID	DUE DATE	INVOICE TOTAL DUE
A-V-ATION LLC	01/16/2026	28370	\$0.00	02/15/2026	\$690.00
HANGAR RENTAL - RENT FOR NEXT MONTH	1.00	\$690.000000	EACH	\$690.00	\$0.00
					\$690.00

✂ DETACH AND RETURN THE PORTION BELOW WITH YOUR PAYMENT ✂



City of Sugar Land
P.O. Box 5029
Sugar Land, Texas 77487-5029

INVOICE

Remit Portion

Invoice Date 01/16/2026
Invoice Number 28370
Customer Number 30001356
Amount Paid

Invoice Total Due \$690.00

A-V-ATION LLC
1000 UPTOWN PARK BLVD.
APT 24
HOUSTON, TX 77056

000001&202630002&370500000690008



105 EDGEVIEW DRIVE
SUITE 300
BROOMFIELD CO 80021-0000

Address Service Requested

- ☐ Check here for change of address (see reverse for details)
☐ Check here for credit card payments (see reverse for details)

LAMINAR HOLDINGS, LLC N820JL
21819 KATY FWY STE 102
KATY TX 77450-1806

Remittance Section

Invoice Number	11473032312260105
Customer Name	LAMINAR HOLDINGS, LLC N820JL
Account Number	011473-032312
Statement Date	1/05/26
Current Charges	\$1,260.00
Due Date	1/31/26
Past Due Amount	\$0.00
Total Amount Due:	\$1,260.00

REMIT PAYMENT TO:
GOGO BUSINESS AVIATION LLC
DEPARTMENT 1371
DENVER CO 80256-0001



Setup Checking Auto Pay

Please make checks payable to: GOGO BUSINESS AVIATION LLC

Summary of Account

Current Service Charges	\$1,260.00
Total Current Charges	\$1,260.00
Previous Bill	\$0.00
Payment Received	\$0.00
Adjustments	\$0.00
Past Due Amount	\$0.00
Recurring Charges	\$525.00
One Time Charges	\$0.00
Usage Charges	\$735.00
Taxes and Surcharges	\$0.00
Total Amount Due	\$1,260.00
Due Date	1/31/26



Invoice Number: 11473032312260105
Account Number: 011473-032312
Statement Date: 1/05/26

Important Messages

GOGO
GALILEO

GLOBAL HIGH SPEED WI-FI
NO MATTER WHAT
OR WHERE YOU FLY.

LEARN MORE: [GOGO.TO/2025-PROMOS](https://gogo.to/2025-PROMOS)

Convenient Payment Options:



Online
<https://gogo.to/myebill>
or your DASH portal



ACH/Wire
To make a payment via
ACH/wire please use
the below instructions:

USBank
ABA#: 102000021
Account #: 103690172665
SWIFT: USBKUS44MT

Send remits to
BA-AR@gogoair.com



Or scan QR code



By Phone
303.301.3278



By Mail
Return stub with
check payment

LTE Network Is Coming - Ensure Your AVANCE Box Is Ready
Gogo's ATG network transitions to LTE in May 2026 - boosting AVANCE L3 speeds by 40% and L5 by 10%. Check your AVANCE Box now: if your serial number ends in "E," you're set. If not, you must swap it to stay connected. We'll provide your LTE replacement box at no cost. Contact your RSM or installing dealer for more information - boxes not replaced before the LTE transition will lose Gogo connectivity.

Taxes and Surcharges on Your Bill

Gogo may assess a monthly Regulatory Cost Recovery Surcharge, which is not a tax nor something we are required to collect by law.
GST/HST no. 817929367RT0001
QST no. 1232827587TQ0001
Gogo imposes a surcharge of 3% or our actual cost of acceptance, whichever is lower, of the transaction amount on credit card purchases. We do not impose a surcharge on debit card purchases. Credit card payments are not accepted from customers in CT, ME, MA, CA, OK, CO.

POSTED



Customer Name
LAMINAR HOLDINGS, LLC N820JL

Account Number
011473-032312

Statement Date
1/5/2026

Detail of Payments and Adjustments

Current Charges Summary for N820JL

Charges for Services

For Dec 2, 2025 To Dec 31, 2025	Qty	Rate	Amount
Pro-Rated: Gogo Biz Data Hourly Plan - Plus	1	.00	.00
Pro-Rated: Hourly Plan - 5 Hours Included	1	525.00	525.00
Pro-Rated: Hourly Plan - Gogo Skyline	1	.00	.00
Pro-Rated: Gogo Vision Standard	1	.00	.00
Pro-Rated: News Clips	1	.00	.00
Total Charges for Services			\$525.00

Package Usage

Pro-Rated: Hourly Plan - 5 Hours Included	Qty	Amount
Rollover Minutes Beginning Balance	.00	
+ Minutes Minimum Billed	300.00	
+ Minutes Overage	420.00	735.00
- Minutes Used	720.00	
- Rollover Minutes Expired	.00	
Rollover Minutes Ending Balance	.00	

Total Package Usage **\$735.00**

Total Current Charges Summary for N820JL **\$1,260.00**

Usage Detail

Date	Time	Description	Type	Detail	Units	Amount
USAGE FOR N820JL						
Gogo Biz Data 341100031007E						
12/6	12:00P	Internet		VARIOUS	195.00	.00
12/26	12:00P	Internet	x	VARIOUS	210.00	183.75
12/29	12:00P	Internet		VARIOUS	315.00	551.25
Totals For Gogo Biz Data 341100031007E					720.00	\$735.00
Totals For N820JL					720.00	\$735.00

Usage for GoGo data – Allocate the bills based on who was in control of the plane on these dates

Usage Detail						
Date	Time	Description	Type	Detail	Units	Amount
USAGE FOR N820JL						
Gogo Biz Data 341100031007E						
12/6	12:00P	Internet - <i>Travis</i>		VARIOUS	195.00	.00
12/26	12:00P	Internet - <i>Tony</i>	x	VARIOUS	210.00	183.75
12/29	12:00P	Internet - <i>Tony</i>		VARIOUS	315.00	551.25
Totals For Gogo Biz Data 341100031007E					720.00	\$735.00
Totals For N820JL					720.00	\$735.00



MILLION AIR
SAN ANTONIO

AVFUEL LOCATION

Million Air - SAT
SAT/KSAT
210-828-8181
info.sat@millionair.com
www.millionair.com/sat

01/02/2026

14:18:54

Sale

Receipt No.: 146334
Batch No.: 5578
Terminal ID: 10290018695
Merchant No.: 2935
Entered By: candace peets

Customer Name:
Card Type: American Express
Card No.: *****1026 Keyed
Exp Date: 12/28
Auth No.: 102278
Tail No.: N820JL
Destination:
License/Reg No.:
Delivered On: 01/02/2026

Jet A Fuel with FSII 422.00
Additive
100 US Gallon @ 4.22000 /GAL

Total (USD) 422.00

Customer Signature

Order Complete

Tuesday, January 6, 2026 at 10:55 AM



Your order is complete. Enjoy!

Order dropped off

If you are having trouble finding your order, message your Dasher or tap Help.



Your Dasher
Miguel Angel



Chick-fil-A
25 Items



11× Chick-fil-A® Chicken Sandwich
\$75.79
Buttery White Bun, Chick-fil-A® Sauce



1× 8oz Barbeque Sauce
\$3.89



1× 8oz Chick-fil-A® Sauce
\$3.89



11× Chick-fil-A Waffle Potato Fries®
\$37.95
Medium Chick-fil-A Waffle Potato Fries®



1× Gallon Beverages
\$8.45
Gallon Freshly-Brewed Iced Tea Sweetened

Subtotal	\$129.97
Delivery Fee	\$2.99
Service Fee ⓘ	\$9.99
Estimated Tax ⓘ	\$10.01

Dasher Tip\$12.23▲

Total\$165.19



Payment\$165.19

Amex....4015 · 1/5/2026 · 10:35 AM



Address

5360 Northwest 20th Terrace
Fort Lauderdale, FL 33309



Leave at lobby



Try DashPass now, get instant credits

You'll receive a \$6.48 credit on this order with a free DashPass trial.

→



Create a business profile

Keep track of your business receipts

Create

Kristie Miller

From: David T Stewart <dstewart@highlandview.net>
Sent: Tuesday, January 6, 2026 11:52 AM
To: Kristie Miller
Subject: Fw: Your Petroleum Service Company Order Confirmation (#259400)

R/T....Cirrus Oil

-- David Tod Stewart II

From: Petroleum Service Company <sales@petroleumservicecompany.com>
Sent: Tuesday, January 6, 2026 11:46:54 AM
To: David T Stewart <dstewart@highlandview.net>
Subject: Your Petroleum Service Company Order Confirmation (#259400)



SINCE 1930
PETROLEUM SERVICE COMPANY
THE PIONEER OF ONLINE PETROLEUM SALES

[Order History](#) | [My Account](#)

ORDER CONFIRMATION

David Stewart thank you for your order!

[To view your order status click here](#)

Order Details

Order #: 259400

Shipping Method:
* (Ground) for \$27.18

Order Total: \$101.00

PURCHASED PRODUCTS



**Phillips 66 X/C Aviation Oil 20w-50
Engine Oil**

SKU: 1045457

Brand: Phillips 66 Aviation

Size Options: 12/1 Quart Case

Item Price: \$73.82

Qty: 1

\$73.82

POSTED

Subtotal: \$73.82

Shipping: \$27.18

PA Sales Tax: \$0.00

Grand total: \$101.00

Payment Method: Credit Cards

Shipping Information

David Stewart
dtstewart@highlandview.net
351 N Post Oak Ln
Apt 705
Houston, Texas 77024
United States
7133018379

Billing Information

David Stewart
351 N Post Oak Ln
Apt 705
Houston, Texas 77024
United States
7133018379

This email confirms that we have received your order. We will send you another email as soon as it is processed and ships. Please verify the products in this email. If there are any changes/concerns please contact customer service immediately.

Follow Us on Social



Subscribe to Our Monthly
Newsletter

[Subscribe Here](#)

Save Our Free Web
App to Your Devices

 &  Compatible

Kristie Miller

From: David T Stewart <dtstewart@highlandview.net>
Sent: Tuesday, January 6, 2026 11:50 AM
To: Kristie Miller
Subject: Fw: Order M2057163 confirmed

R/T....Honda cleaning

-- David Tod Stewart II

From: Meguiar's Direct <orders@meguiarsdirect.com>
Sent: Tuesday, January 6, 2026 11:41:24 AM
To: David T Stewart <dtstewart@highlandview.net>
Subject: Order M2057163 confirmed



ORDER M2057163

Thank you for your purchase!

We're getting your order ready to be shipped. We will notify you when it has been sent.

[View your order](#)

or [Visit our store](#)

[Order summary](#)

POSTED



**Meguiar's Final Inspection Wipe-off Detailer, M34 - 16
oz. x 1**

\$9.99

Subtotal **\$9.99**

Shipping **\$7.95**

Taxes **\$0.00**

Total **\$17.94 USD**

Customer information

Shipping address

David Stewart

351 North Post Oak Lane

705

Houston TX 77024

United States

Billing address

David Stewart

351 North Post Oak Lane

705

Houston TX 77024

United States

Shipping method

Economy Shipping

If you have any questions, reply to this email or contact us at orders@meguiarsdirect.com

Kristie Miller

From: David T Stewart <dtstewart@highlandview.net>
Sent: Tuesday, January 6, 2026 11:50 AM
To: Kristie Miller
Subject: Fw: Aircraft Spruce Order Confirmation 17820029

R/T....Honda cleaning

-- David Tod Stewart II

From: Aircraft Spruce <donotreply@aircraftspruce.com>
Sent: Tuesday, January 6, 2026 11:32:11 AM
To: David T Stewart <dtstewart@highlandview.net>
Subject: Aircraft Spruce Order Confirmation 17820029



1-877-477-7823 Contact Us

My Account  Shop 

Order Date:
01/06/26

Order Number:
17820029

DAVID STEWART,

Thank you for your order. Your order has been placed and is being processed. Once your order ships, we'll reach back out with another email to let you know.

Your Order

Shipment 1: Expected to deliver Monday, Jan. 12 from TX via  Priority Mail

POSTED



**REALCLEAN ADVAN
UPHOLSTERY CLNR AND STAIN
REMOVER 32 OZ**

Part #: 09-03778
Mfr Part #: ADV32

\$17.95 / EA

Quantity
1.00

\$17.95

Special Instructions

Total

Merchandise
Total: **\$17.95**

Quoted Shipping: **\$8.65**

Tax: **\$2.19**

Total (USD) \$28.79

Shipping & Billing Details

Shipping Address: DAVID STEWART 351 N POST OAK LN 705
HOUSTON, TX 77024

Billing Address: DAVID STEWART 351 N POST OAK LN APT 705
HOUSTON, TX 77024

Payment Method: CREDIT CARD

Kristie Miller

From: David T Stewart <dtstewart@highlandview.net>
Sent: Tuesday, January 6, 2026 11:50 AM
To: Kristie Miller
Subject: [Junk released by Allowed List] Fw: AERO Specialties order receipt from January 6, 2026

R/T....Honda cleaning

-- David Tod Stewart II

From: AERO Specialties <sales@aerospecialties.com>
Sent: Tuesday, January 6, 2026 11:26:04 AM
To: David T Stewart <dtstewart@highlandview.net>
Subject: AERO Specialties order receipt from January 6, 2026



Thank you for your order

Hi David,

Just to let you know — we've received your order #106158, and it is now being processed:

[Order #106158] (January 6, 2026)

POSTED

Product	Quantity	Price
Ultra Soft Upholstery Conditioner, 19 oz.	2	\$47.98 USD

Subtotal:	\$47.98 USD
Shipping:	\$22.05 USD via UPS Ground
Tax:	\$4.38 USD
Payment method:	Credit/Debit Card
Total:	\$74.41 USD

Please contact AERO Specialties at +1 208-378-9888 or
sales@aerospecialties.com with questions or concerns regarding the status of
your order.

Billing address

Shipping address

*David Stewart
351 N Post Oak Ln
705
Houston, TX 77024
United States (US)
+17133018379
dstewart@highlandview.net*

*David Stewart
351 N Post Oak Ln
705
Houston, TX 77024
United States (US)*

Thanks for using www.aerospecialties.com!

Richard & Tony
Hand Cleaning

← Search or ask a question

 **Leather Cleaner Leather Soap...**
Sold by: Aero Cosmetics
\$18.95

[Track package](#) [Problem with order](#)

[Cancel items](#) [Write a product review](#)

[Buy it again](#) [Change Payment Method](#)

Order summary

Order placed January 6, 2026

Order # 112-3163408-0199466

Item(s) Subtotal:	\$18.95
Shipping & Handling:	\$0.00
Total before tax:	\$18.95
Estimated tax to be collected:	\$1.56
Grand Total:	\$20.51

[View invoice](#)

Payment method

AMEX ending in 1026

[View related transactions](#)



Ship to

David Stewart

POSTED

GLOBALSELECT

ROT Maintenance

GlobalSelect - KSGR

Invoice: **INV2600859**

Reference: **WST00025129**

Printed Date: Tuesday, 13 January, 2026 10:28:15 PM

Sales Person: **Vanesa**

Sold To: **A-V-A Aviation, LLC**

Invoice Date: **01/13/2026 22:28**

Billed To: **A-V-A Aviation, LLC**

Due Date: **01/13/2026 22:28**

#	Type	Description	Tail/ID	ICAO	Qty	List Price	Discount	OTD Unit Price	Total
1)	Services	Aircraft Towing	N199TB	SR22	1	\$54.00	\$0.00	\$54.00	\$54.00

Total: **\$54.00**

Payment Information

Response: **APPROVED** AuthCode: **3235905** Payment: **Avcard ***9945** Processing Date: **01/13/2026 22:28 X1-**
Batch#: **000651**

Amount: **\$54.00**

Total Payments: **\$54.00**

Balance Due: **\$0.00**

POSTED

signed

Sold To: **A-V-A Aviation, LLC**
Invoice Date: **01/13/2026 08:36**

Billed To: **A-V-A Aviation, LLC**
Due Date: **01/13/2026 08:36**

#	Type	Description	Tail/ID	ICAO	Qty	List Price	Discount	OTD Unit Price	Total
1)	Services	Aircraft Towing	N199TB	SR22	1	\$54.00	\$0.00	\$54.00	\$54.00
2)	Parking	Ramp Fee	N199TB	SR22	1	\$12.00	\$0.00	\$0.00	\$0.00
3)	Parking	Infrastructure Fee	N199TB	SR22	1	\$3.00	\$0.00	\$0.00	\$0.00

Total: **\$54.00**

Payment Information

Response: **APPROVED** AuthCode: **3232724** Payment: **Avcard ***9945** Processing Date: **01/13/2026 08:36** X1-Batch#: **000649**

Amount: **\$54.00**

Total Payments: **\$54.00**
Balance Due: **\$0.00**

POSTED

signed

INVOICE

INVOICE FROM:
Jetdetail Unlimited

281-914-7466
salazar_alvaro@yahoo.com
18523 Windy Knoll Way Houston, Tx
77084

BILL TO:
David Stewart

Number: Invoice002

Date: Jan 17, 2026

Due date: On receipt

Description	Quantity	Unit price	TAX	Amount
Exterior Detail Full Exterior Detail Top/Bottom wings full body cleaning on fuelsulage/tail/windows. Decrease landing gears. Debug leading edges.	1	\$550.00	0.0 %	\$550.00

Cleaned 1/17/2026

SUBTOTAL: \$550.00
TAX: \$0.00
TOTAL: \$550.00
PAID: \$0.00

BALANCE DUE \$550.00

Comments

N820JL Honda Jet

PAID
POSTED

Kristie Miller

From: Travers & Associates at Simply Easier Payments <no-reply@simply-easier-payments.com>
Sent: Monday, January 26, 2026 11:30 AM
To: Billing 46
Subject: Thank you for your payment.



Your payment offer has been accepted.

Payment Amount	\$14,067.25
Service Fee	\$17.02
Total Amount	\$14,084.27

Billing Information

Name on Check	Laminar Holdings LLC
Routing Number	XXXXXX4149
Account Number	XXXXXX1553
Account Type	CHECKING
Time	Jan 26, 2026 12:29 PM
Submit Date	Jan 26, 2026 12:14 PM
Email	billing@abrhco.com
Confirmation Number	220-111
Payment ID	d8b8c1b27f131166bd810c84ba50df22aefe12f0
Phone Number	281-647-2825
Address	P.O. Box 79
City/State/Zip	Katy, TX 77492

The Payment Amount charge will display as Travers & Associates on your bank statement.

The Service Fee charge will display as SEP INSURANC ACH FEE 919-384-0514 on your bank statement.

Travers & Associates Aviation Insurance
337 W. Lockwood Ave
St. Louis, MO 63119
800-888-9859
accounting@traversaviation.com
www.traversaviation.com

Simply Easier Payments

Receipt

Your payment cannot be processed until all 3 steps below are completed. Completion of this form does not automatically bind coverage.

Step 1

Submit Your Payment Request by filling in this page and clicking the "Next" button.
(Unless the items with an asterisk (*) are completed, your payment request will be declined.)

Step 2

Your Payment Request is reviewed by the company you are paying.

Step 3

You Get an E-mail Notification telling you your payment request has been accepted or declined.

If your payment request is accepted, the date and time of acceptance will reflect the time of submission. This date and time will show on your payment submission acknowledgment.

IMPORTANT NOTE: Your payment is not made until you receive an e-mail notification. You should receive this no later than the next business day after you submit your payment request.




Account Name	Laminar Holdings LLC
Client ID	108728
N Number	N820JL

Payment Amount	\$14,067.25
Service Fee	\$17.02
Total Amount	\$14,084.27

Routing Number	XXXXX4149
Account Number	XXXXX1553
Account Type	CHECKING
Check Number	
Confirmation Number	
Time	Jan 26, 2026 12:14:22 PM

Billing Information

Name as shown on check	Laminar Holdings LLC
Street	P.O. Box 79
City	Katy
State	TX
Zip/Postal Code	77492
Email Address	billing@abrhco.com
Phone Number (XXX-XXX-XXXX)	281-647-2825



The Payment Amount charge will display as "Travers & Associates" on your bank statement.

The Service Fee charge will display as "SEP INSURANC ACH FEE 919-384-0514" on your bank statement.

**Houston Aviation Center, LLC**

12888 Hwy 6 S Ste 113
 Sugar Land, TX 77498 USA
 Phone: 281-494-5800
 Fax: 281-494-5803
 Email: hac@houston-aviation.com
 Date: 1/26/2026, 3:58 PM

CUSTOMER INFORMATION**A-V-ATION LLC**

1000 UPTOWN PARK BVLD #24
 HOUSTON, TX 77056
 212-748-3337
 tonybradfield@me.com
 Reg. No: N199TB
 2020 Cirrs SR22T
 Current A/C TT: 875.7, Hobbs: 1042.7
 A/C Serial: 2109

Customer Invoice**Work Order: 6953-10-2025****Total Balance Due \$8,888.14 (See Below For Cost Detail)****Item: 1 - Airworthy Airframe****Discrepancy**

Annual Inspection (Airframe log book entry)

Hours

Flat

Subtotal

4,830.00

Flight Meter: 875.7

Hobbs: 1042.7

Corrective Action

(Flight Meter: 875.7) Completed an Annual Inspection Ref. CDC SR22T AMM 5-20. ELT 1000 was inspected and tested per FAR 91.207(d). Battery exp. JUL/2026. Complied with 12 month cabin fire extinguisher inspection (weight 2 lbs. 6.6 oz.). Complied with Precise Flight Fixed Oxygen System Instructions for Continued Airworthiness Ref. Document 102NMN0003 Par 2.7.1. Visually inspected cabin heat mixing valve. Lubricated engine cowling access panel door, baggage door hinge and seat tracks. Checked ADs thru BW 2025-24. AD 2024-24-11 Amendment 39-22902, Upper Power Lever, is initially due when the upper power lever accumulates 1,200 hrs. TIS.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	MS24665-283	Cotter pin (AN380-3-3) (Taxed)		0.10	0.10
1	EA	MS29513-137	Seal O Ring Fuel .103 T X 2.050 ID (Taxed)		2.10	2.10
1	EA	NAS1523-8B	Stat-O-Seal (Taxed)		6.40	6.40

Labor: \$4,830.00**Parts: \$8.60****Shipping: \$0.00****Item Subtotal: \$4,838.60****Item: 2 - Airworthy Engine****Discrepancy**

Annual Inspection (Engine log book entry)

Hours

0.00

Subtotal

0.00

Corrective Action

(Flight Meter: 875.7) Completed a 100 HR/Annual Inspection Ref. CDC SR22T AMM 5-20 & Continental Aerospace Technologies M-0. Performed a cylinder compression check Ref. Continental Aerospace Technologies M-0, using differential compression tester with a calibrated orifice value of 46 PSI with results as follows: #1/74, 2/62, 3/58, 4/66, 5/74, 6/68 over 80 PSI. Inspected oil filter for contaminants (no sample taken). Installed new oil filter P/n AA48108-2 and serviced engine with 8 Qts. Phillips X/C 20W-50. Ran engine and checked filter for leaks. Inspected and tested Continuous Flow Fuel Injection system per Continental Aerospace Technologies M-18 and M-0. Removed and cleaned all fuel injector nozzles. Reinstalled fuel injectors in their designated positions using new o-rings P/n 630979-9. Inspected intake and exhaust system for leaks. Cleaned, gapped and tested spark plugs. Operational check satisfactory. Checked ADs thru BW 2025-24.

POSTED

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
12	EA	630979-9	O-ring, Fuel Injector Nozzle (Taxed)		3.65	43.80
1	EA	AA48108-2	Oil filter, Tempest (Taxed)		53.87	53.87
8	EA	Oil 20W-50 PH	PHILLIPS X/C 20W-50 (Taxed)		8.88	71.04
1		Oil-Disposal	Oil disposal fee. (Disposal of oil and oil filter)(per engine)		2.00	2.00
12	EA	U674	TEMPEST COPPER SPARKPLUG GASKET (Taxed)		1.13	13.56
1		Varsol	Engine Wash Varsol (Taxed)		8.25	8.25

Labor: \$0.00**Parts: \$192.52****Shipping: \$0.00****Item Subtotal: \$192.52**

Item: 3 - Airworthy Prop

	Hours	Subtotal
Discrepancy Annual Inspection (Propeller log book entry)	0.00	0.00

Corrective Action

(Flight Meter: 875.7) Completed a 100 HR/Annual Inspection Ref. CDC SR22T AMM 5-20 and Hartzell Propeller Owner's Manual No. 145. Inspected propeller blades and ice feed shoes. Inspected and lubricated propeller hub. Checked blade track. Checked ADs thru BW 2025-24.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 4 - Airworthy Airframe

	Hours	Subtotal
Discrepancy Airworthiness Directive & Mandatory Service Bulletin Research.	0.00	0.00

Corrective Action

(Flight Meter: 875.7) Researched all ADs and Mandatory Service Bulletins thru BW 2025-24. AD 2024-24-11 Amendment 39-22902, Upper Power Lever, is initially due when the upper power lever accumulates 1,200 hrs. TIS. C/W SB2X-55-15R1 "Rudder Hinge Inspection" by inspecting the rudder hinge for damage along the aft edge, hinge flange radius for damage, and rivet condition using a borescope. Rudder hinges and rivets are in satisfactory condition. C/W SB2X-95-38 "CAPS Activation Handle Inspection by inspecting the CAPS activation handle for security. CAPS handle is secured. No further action required.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 5 - Airframe AD

	Hours	Subtotal
Discrepancy AD 2024-24-11 Amendment 39-22902, Upper Power Lever.	0.00	0.00

To terminate the applicability of the AD, a replacement power lever is available through compliance with SB2X-76-07. Part cost \$212.96, labor \$280.00

Corrective Action

AD 2024-24-11 Amendment 39-22902, Upper Power Lever, is initially due when the upper power lever accumulates 1,200 hrs. TIS.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 6 - Airframe SB

	Hours	Subtotal
Discrepancy SB2X-55-15R1 "Rudder Hinge Inspection".	0.50	70.00

Cirrus Mandatory Service Bulletin
Labor is for the inspection of rudder hinges and rivets - if repair is required, labor is 6.5 hrs.

Corrective Action

C/W SB2X-55-15R1 "Rudder Hinge Inspection" by inspecting the rudder hinge for damage along the aft edge, hinge flange radius for damage, and rivet condition using a borescope. Rudder hinges and rivets are in satisfactory condition.

Labor: \$70.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$70.00
-----------------------	----------------------	-------------------------	-------------------------------

Item: 7 - Airframe SB

	Hours	Subtotal
Discrepancy SB2X-95-38 "CAPS Activation Handle Inspection".	0.25	35.00

Cirrus Mandatory Service Bulletin

Corrective Action

C/W SB2X-95-38 "CAPS Activation Handle Inspection by inspecting the CAPS activation handle for security. CAPS handle is secured. No further action required.

Labor: \$35.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$35.00
-----------------------	----------------------	-------------------------	-------------------------------

Item: 8 - Engine-Misc.

Discrepancy	Hours	Subtotal
Borescope findings.	0.00	0.00

Corrective Action

#1 Good cross hatching. Good exhaust valve burn pattern, seat, and stem. Good intake valve and stem conditions.
#3 Good cross hatching. Good exhaust valve burn pattern, seat, and stem. Good intake valve and stem conditions.
#5 Good cross hatching. Good exhaust valve burn pattern, seat, and stem. Good intake valve and stem conditions.
#2 Good cross hatching, but piston pin contact on the FWD side of the cylinder. Piston head and cylinder head are wet with oil, and cylinder has marginal oil pooling. Good exhaust valve burn pattern and seat, but stem shows has some oil pushing past. Good intake valve, but stem has slight amount of oil pushing past.
#4 Good cross hatching. Piston head and cylinder head are wet with oil, and cylinder has marginal oil pooling. Good exhaust valve burn pattern and seat, stem. Good intake valve and stem.
#6 Good cross hatching, but minor oil pooling. Good exhaust valve burn pattern, seat, and stem. Good intake valve and stem conditions.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 9 - Engine Recommended

Discrepancy	Hours	Subtotal
ALT 1 500 hr. recommended service is past due (Due at FM: 757.4)	3.00	420.00

Corrective Action

Performed 500 hr. ALT 1 inspection IAW Hartzell Engine Technologies Aircraft Alternator Owner's Manual P/n EESS11003311. Removed alternator and removed brush holder. Inspected each brush for wear, and found brushes worn beyond limits. Installed new brush holder assy. P/n ALE-3045BS and reinstalled alternator with new gasket P/n 653981. Function check satisfactory. Next due FM: 1375.7.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		653981	Gasket Alternator (Taxed)		8.09	8.09
1		ALE-3045BS	Carbon Brush Holder (Taxed)		327.99	327.99

Labor: \$420.00	Parts: \$336.08	Shipping: \$0.00	Item Subtotal: \$756.08
------------------------	------------------------	-------------------------	--------------------------------

Item: 10 - Engine Recommended

Discrepancy	Hours	Subtotal
ALT 2 500 hr. recommended service is past due (due at FM: 757.4).	1.75	245.00

May require brushes.

Corrective Action

Performed 500 hr. ALT 2 inspection IAW Hartzell Engine Technologies Aircraft Alternator Owner's Manual P/n PP2001. Removed alternator and removed brush holder. Inspected each brush for wear, and found within wear limits. Reinstalled alternator. Function check satisfactory. Next due FM: 1375.7.

Labor: \$245.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$245.00
------------------------	----------------------	-------------------------	--------------------------------

Item: 11 - Engine Recommended

Discrepancy	Hours	Subtotal
RH Magneto 500 hr. recommended inspection/repair or replacement is past due (due at FM: 757.6).	1.50	210.00

Corrective Action

Removed RH magneto P/n 10-500556-101, S/N D21BA173. Installed new RH magneto P/n 10-500556-101, S/N D25IA039. Installed new magneto gasket P/n 649954 and new intake manifold gasket P/n 649950. Timed RH to LH magneto.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	10-500556-101	Magneto, Bendix (Ship: 13.35) (Taxed)		2,752.78	2,752.78
1		649950	Intake Manifold Gasket (Taxed)		2.69	2.69
1		649954	Gasket, Magneto (Taxed)		1.97	1.97

Labor: \$210.00	Parts: \$2,757.44	Shipping: \$13.35	Item Subtotal: \$2,980.79
------------------------	--------------------------	--------------------------	----------------------------------

Item: 12 - Engine Recommended

Discrepancy	Hours	Subtotal
Turbo induction air filters are very dirty, recommend replacing.	0.50	70.00

Corrective Action

Installed (2) new turbo induction air filters P/n 27166-001.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
2		27166-001	SCD, Air Filter, TCM Turbo (Taxed)		133.00	266.00

Labor: \$70.00	Parts: \$266.00	Shipping: \$0.00	Item Subtotal: \$336.00
-----------------------	------------------------	-------------------------	--------------------------------

Item: 13 - Airframe Recommended

Discrepancy	Hours	Subtotal
TKS panels are very dirty and aren't completely wetting out, recommend cleaning.	1.00	140.00

Corrective Action

Cleaned TKS panels. Function check satisfactory.

Labor: \$140.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$140.00
------------------------	----------------------	-------------------------	--------------------------------

Item: 14 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Precise Flight 5 yr. regulator overhaul and cylinder hydrostatic testing was due 5/25.	2.00	280.00

Note: Can return to service with cylinder removed and placarded INOP as well as weight & balance amendment to POH.

Corrective Action

Removed Precise flight oxygen system P/n 099N0025-2 REV B, S/N HPR102993. Installed OXYGEN INOP placard over oxygen switch. Amended aircraft weight and balance.

Labor: \$280.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$280.00
------------------------	----------------------	-------------------------	--------------------------------

Item: 15 - Customer Rejected

Discrepancy	Hours	Subtotal
CAPS reefing line cutters 6 yr. life limited replacement will be due: 02/2026.	Rejected	0.00

Note: Line cutters must be replaced by the end of Feb/2026.

Corrective Action

Customer deferred corrective action at this time.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 16 - Airframe Recommended

Discrepancy	Hours	Subtotal
NLG oleo strut is low on nitrogen.	0.30	42.00

Corrective Action

Serviced oleo strut with nitrogen.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		Nitrogen	Nitrogen Fill (Taxed)		10.00	10.00

Labor: \$42.00	Parts: \$10.00	Shipping: \$0.00	Item Subtotal: \$52.00
-----------------------	-----------------------	-------------------------	-------------------------------

Item: 17 - Airframe Recommended

Discrepancy

NLG strut fairing is chafing against NLG strut in a few areas.

Hours	Subtotal
0.25	35.00

Can apply chafe tape.

Corrective Action

Installed new chafe tape P/n LE-02C on NLG strut to prevent chafing.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		LE-02C	Leading edge tape, clear, 2", per ft. (Taxed)		1.63	1.63

Labor: \$35.00	Parts: \$1.63	Shipping: \$0.00	Item Subtotal: \$36.63
-----------------------	----------------------	-------------------------	-------------------------------

Item: 18 - Airworthy Airframe

Discrepancy

Nose fork tension high at 43 lbs; range is 20-25 lbs.

Hours	Subtotal
1.00	140.00

Will need to remove and inspect. May require new thrust washer and Belleville washers.

Corrective Action

Cleaned corrosion from spindle cup and nose fork bearing halves. Installed new thrust washer P/n 50545-001 and new castellated nut P/n MS17825-8, with new cotter pin P/n MS24665-355. Set nose fork tension to 30 lbs. Ref CDC SR22T AMM 32-20.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		50545-001	Thrust Washer (Taxed)		14.00	14.00
1		MS17825-8	Castellated Nut (Taxed)		10.61	10.61
1	EA	MS24665-355	Cotter Pin (AN380-4-5) CAD (Taxed)		0.28	0.28

Labor: \$140.00	Parts: \$24.89	Shipping: \$0.00	Item Subtotal: \$164.89
------------------------	-----------------------	-------------------------	--------------------------------

Item: 19 - Airframe Recommended

Discrepancy

Upper and lower piano hinges on NLG strut fairing are chipped off, and upper NLG strut hinge tab is also chipped.

Hours	Subtotal
2.00	280.00

Note: We can splice in and bond a new section of hinge material on fairing but will have to replace tab.

Corrective Action

Installed new structural hinge P/n MS20001P4 on upper and lower sections of NLG strut fairing, using new rivets P/n MS20426AD4-3 and epoxy P/n 50008-001U. Installed new NLG upper strut fairing hinge tab P/n 26960-104 with (2) new rivets P/n MS20470AD4-4.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	26960-104	Hinge Tab (Taxed)		3.03	3.03
3		MS20001P4	Hinge Extruded Structural 1.500 Wide, per inch 3ft (Taxed)		3.98	11.94
2		MS20426AD4-3	Rivet Aluminum Solid 1/8 D X 3/16 (Taxed)		0.04	0.08
2		MS20470AD4-4	Rivet Aluminum Solid 1/8 D X 1/4 (Taxed)		0.04	0.08

Labor: \$280.00	Parts: \$15.13	Shipping: \$0.00	Item Subtotal: \$295.13
------------------------	-----------------------	-------------------------	--------------------------------

Item: 20 - Airworthy Airframe

Discrepancy	Hours	Subtotal
LH & RH tires are worn to limits on the OB tread.	2.50	350.00

Corrective Action

Installed new LH tire and RH tire P/n 025-501-0, LH S/N 5060T00138 and RH S/N 5060T00170 with (2) new wheel o-rings P/n J-JTR-007N and (2) new cotter pins P/n MS24665-360. Inflated tires to 65 psi and checked for leaks.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
2		025-501-0	Michelin Pilot, 15X6.0-6/6 ply (Taxed)		449.72	899.44
2		J-JTR-007N	Beringer o-ring, main (Taxed)		6.04	12.08
2		MS24665-360	Cotter pin (AN380-4-8) (Taxed)		0.21	0.42
2		Tire-Disposal	Tire Disposal Fee		5.00	10.00

Labor: \$350.00 Parts: \$921.94 Shipping: \$0.00 Item Subtotal: \$1,271.94

Item: 21 - Airframe-Misc.

Discrepancy	Hours	Subtotal
LH horizontal stabilizer TKS panel strip sealant is deteriorating/sticky.	1.00	140.00

Corrective Action

Applied new TKS panel strip sealant P/n 3M 760UV along the LH horizontal stabilizer root fairing and TKS panel.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
2	EA	3M 760UV	Sealant, black, per oz. (Taxed)		4.43	8.86

Labor: \$140.00 Parts: \$8.86 Shipping: \$0.00 Item Subtotal: \$148.86

Item: 22 - Airframe Recommended

Discrepancy	Hours	Subtotal
Throttle cable grommet on LH AFT baffle is torn.	0.25	35.00

Corrective Action

Installed new throttle cable grommet P/n AN931-5-12 on LH AFT baffle.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		AN931-5-12	Grommet, 5/16 ID, 1 OD, 3/4" (MS35489-10) (Taxed)		1.10	1.10

Labor: \$35.00 Parts: \$1.10 Shipping: \$0.00 Item Subtotal: \$36.10

Item: 23 - Airframe Recommended

Discrepancy	Hours	Subtotal
Adel clamp on lower LH engine mount to drain hose has deteriorated.	0.28	39.20

Corrective Action

Installed new adel clamp P/n MS21919WDG16 on lower LH engine mount.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		MS21919WDG16	Clamp Cushion 1" ID (Taxed)		3.17	3.17

Labor: \$39.20 Parts: \$3.17 Shipping: \$0.00 Item Subtotal: \$42.37

Item: 24 - Airframe Recommended

Discrepancy	Hours	Subtotal
TKS filter element is past due for 24 mo. recommended replacement (due 01/2025).	1.01	141.40

Corrective Action

Installed new TKS filter element P/n 21986-203 with new o-ring P/n AS3582-235 and (2) new seal rings P/n 15164-094B. Purged lines. Leak and operational check satisfactory.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
2		15164-094B	Seal ring 1/2-bulk (Taxed)		2.82	5.64
1		21986-203	Filter Element, TKS (Ship: 35.00) (Taxed)		793.35	793.35
1		AS3582-235	o-ring 3 1/8 ID (21986-206 eqv) (Taxed)		1.77	1.77

Labor: \$141.40	Parts: \$800.76	Shipping: \$35.00	Item Subtotal: \$977.16
------------------------	------------------------	--------------------------	--------------------------------

Item: 25 - Airframe Recommended

Discrepancy	Hours	Subtotal
TKS fluid level is low (LH 1.2 GAL. RH 0.9 GAL.)	0.30	42.00

Corrective Action

Serviced LH and RH TKS reservoirs to 3.5 gal. each with deice fluid P/n AVL-TKS.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
4.9		AVL-TKS	Deice fluid, per gal. (Taxed)		22.00	107.80

Labor: \$42.00	Parts: \$107.80	Shipping: \$0.00	Item Subtotal: \$149.80
-----------------------	------------------------	-------------------------	--------------------------------

Item: 26 - Customer Rejected

Discrepancy	Hours	Subtotal
Several databases are expiring/expired.	Rejected	0.00

Can update databases; need to verify Jeppesen account information

Corrective Action

Customer deferred corrective action at this time.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 27 - Airframe Recommended

Discrepancy	Hours	Subtotal
Small section of co-pilot door seal is separated at RH FWD side.	0.25	35.00

Can re-bond.

Corrective Action

Reattached separated section of co-pilot door seal with adhesive.

Labor: \$35.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$35.00
-----------------------	----------------------	-------------------------	-------------------------------

Item: 28 - Airframe-Misc.

Discrepancy	Hours	Subtotal
Pilot side passenger window and paint has a scratch that starts at grab handle and extends into the window. Glass scratch is too deep to polish. Would have to be addressed (if you wish) by Lee Aerospace.	0.00	0.00

Corrective Action

For informational purposes.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 29 - Airframe-Misc.

Discrepancy

RH cabin coat hanger hook is loose.

Hours	Subtotal
0.47	65.80

Can re-tighten screw.

Upon further inspection, screw is extremely stripped and needs replacement.

Corrective Action

Installed new screw P/n 50835-012 on RH cabin coat hanger hook.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	50835-012	BUTTON HEAD CAP SCREW (Taxed)		0.79	0.79

Labor: \$65.80	Parts: \$0.79	Shipping: \$0.00	Item Subtotal: \$66.59
-----------------------	----------------------	-------------------------	-------------------------------

Item: 30 - Airworthy Airframe

Discrepancy

(2) Cable tie anchor mounts securing TKS line bundle at AFT fuselage is disbonded. (bundle can chafe into control cable if another anchor mount becomes disbonded).

Hours	Subtotal
0.54	75.60

Recommend replacing anchor mount.

Corrective Action

Installed (2) new cable tie anchors P/n 50132-001 using epoxy P/n 50080-001U. Secured TKS line bundle at AFT fuselage with cable ties.

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		50080-001U	Vibra-tite, green, epoxy, 5 minute, 2-part cartridge (Taxed)		31.62	31.62
2		50132-001	EMS-A-DO Holder, tie down restraint (Taxed)		2.16	4.32

Labor: \$75.60	Parts: \$35.94	Shipping: \$0.00	Item Subtotal: \$111.54
-----------------------	-----------------------	-------------------------	--------------------------------

Item: 31 - Airworthy Airframe

Discrepancy

Annual inspection (Airframe certification statement only)

Hours	Subtotal
0.00	0.00

Corrective Action

I certify that this Airframe has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 32 - Airworthy Engine

Discrepancy

Annual inspection (Engine certification statement only)

Hours	Subtotal
0.00	0.00

Corrective Action

I certify that this Engine has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Item: 33 - Airworthy Prop

Discrepancy

Annual inspection (Propeller certification statement only)

Hours	Subtotal
0.00	0.00

Corrective Action

I certify that this Propeller has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
----------------------	----------------------	-------------------------	------------------------------

Please see the next page for the totals for this invoice

Additional Charges							Subtotal
Pilot Services	Tire Disposal	EPA Charge	Oil Analysis	Shop Supplies	Fuel	Misc.	
0.00	0.00	0.00	0.00	0.00	0.00	0.00	\$0.00

Labor Summary

Shop Labor: \$7,721.00 Outside Repair: \$0.00

55.16 hours were needed to complete this Work Order

Total Labor:	\$7,721.00
Total Parts:	\$5,492.65
Total Shipping:	\$48.35
Additional Charges:	\$0.00
Tax:	\$456.14
Amount Due:	\$13,718.14
Deposits & Credits:	\$4,830.00
Balance Due:	\$8,888.14

Important Information

INVOICES ARE DUE UPON RECEIPT

If utilizing a credit card for payment, a 3% credit card processing fee will be assessed on invoice totals of \$10,000.00 or more.

We greatly appreciate your business!

A-V-ACTION LLC or Authorized Representative

Date

Turbine Aircraft Logistics, LLC

5190 Calmes Way
Pitt Island, FL 32952 US
+13863858436
carson@turbineaircraftlogistics.com



INVOICE

BILL TO
Richard Hodge
Laminar Holdings, LLC
PO Box 79
Katy, TX 77492

SHIP TO
Richard Hodge
Laminar Holdings, LLC
PO Box 79
Katy, TX 77492

INVOICE 2293
DATE 01/31/2026
TERMS Net 30
DUE DATE 03/02/2026

ACTIVITY	DATE	QTY	RATE	AMOUNT
Products Purchased for Managed Aircraft:Products Purchased for Managed Aircraft N820JL Steal Shot Ballast Weight for Forward Baggage Compartment	12/26/2025	1	268.00	268.00
09-04590-10 iCloth Avionics Cleaner 10 Pack	12/26/2025	2	3.95	7.90
4765 Mobil II Turbine Oil	12/26/2025	4	22.33	89.32
AC9165 Windshield Cleaning Cloths	12/26/2025	1	20.57	20.57
Products Purchased for Managed Aircraft:Aircraft Parts:Aero Cosmetics Micro Fiber Towels Aero Cosmetics Micro Fiber Towels	12/26/2025	1	10.90	10.90
Shipping Aircraft Spruce Shipping	12/26/2025	1	17.98	17.98
Products Purchased for Managed Aircraft:Products Purchased for Managed Aircraft Aircraft Spruce Sales Tax	12/26/2025	1	11.20	11.20

SUBTOTAL	425.87
TAX	0.00
TOTAL	425.87

BALANCE DUE USD 425.87

Pay invoice