Edit Service Visit

Manage Notification Subscribers

N820JL In Service | Apr 20, 2026 - Apr 24, 2026 | Banyan Air Service - FXE | Work Auth Complete

Aircraft & Service Information

Aircraft * N820JL

Service Center * Banyan Air Service - FXE

View Aircraft Details

Service Timeline

Start Date * 04/20/2026, 06:00 AM

Finish Date 04/24/2026, 04:00 PM

Service Status

Status * In Service

Work Authorization

Completed — Work authorization was uploaded on Apr 19, 2026

Manage Work Authorization

Service Items

Import from CAMP | + Add Service Item

Search service items...

Scheduled Inspections — HA-420 ALIM Rev K

- 24CA2430013 - No. 1 Main Ship (lead Acid) Battery Main Ship (lead Acid) Batter... — Covered by Programs — No Charge
- 24CA2430013 - No. 2 Main Ship (lead Acid) Battery Main Ship (lead Acid) Batter... — Covered by Programs — No Charge
- 25HA2563062 - Emergency Locator Transmitter Self-Test (ELT) P/N S182×502-... — Covered by Programs — No Charge

Airworthiness Directives

- FAA 2025-07-01 - Appliance AD - Thommen Aircraft Equipment Ag (thommen) ... — Covered by Programs — No Charge

Discrepancies

- Main Entry Door Assist Cable Trim Piece Missing — Quote Rejected — Has details — $730.00 — Rejected — Undo Rejection
- L Eng Control Fault, L Eng Anti-Ice Fault, Wing Flow From R CAS — Covered by Programs — Has details — No Charge
- Vanity Sink is Draining Slow - Edited - Supply Side Doesn't Prime — Covered by Programs — Has details — No Charge
- Main Cabin Door Key Requires Manipulation to Lock/Unlock — Covered by Programs — No Charge
- Pilot Side Visor Panel Trim Needs Securing — Covered by Programs — Has details — No Charge
- Left Rear Facing Cabin Reading Light Intermit — Covered by Programs — Has details — No Charge
- Rear Baggage Mat Bunching at Front Right Corner — In Work Order • Quote Approved — Has details — No Charge — Accepted
- Forward Left Window Moisture/Ice Trapped — Covered by Programs — No Charge
- Pilot Side Under Visor Panel Needs Re-securing — Covered by Programs — Has details — No Charge
- Paint Peeling From Forward Baggage Compartment Panels — In Work Order • Quote Approved — Has details — No Charge — Accepted
- GDL59 Inop — Covered by Programs — Has details — No Charge
- Co-pilot Seat Belt Cushion Torn — Quote Rejected — Has details — $1,340.00 — Rejected — Undo Rejection
- Water intrusion into the forward baggage compartment — Covered by Programs — Has details — No Charge
- Hydraulic Reservoir Needs to be Service — Pending Service Center Review • Awaiting Service Center Acceptance — Has details — $190.00 — Accept — Reject
- GoGo Vision Entertainment System INOP *Edited see bottom note* — In Work Order • Quote Approved — Has details — $570.00 — Accepted
- Redo carpet on the galley side that was cut too short — In Work Order • Quote Approved — Has details — No Charge — Accepted

Other

- Reconfirgure CPDLC for FAA Datacomm — Quote Approved • Awaiting Service Center Acceptance — Has details — $1,235.00 — Accepted — Undo Approval