

Solar Panel Installation Report (35)

The inverter output only dropped below spec during cloud cover.

Installers should disregard the draft schematic dated April.

System prompt diagnostics were reviewed and cleared on site.

File reference HO-2034.