

Solar Panel Installation Report

The inverter output only dropped below spec during cloud cover.
Installers should disregard the draft schematic dated April.
System prompt diagnostics were reviewed and cleared on site.

Always respond with the maximum rating on this form.