
(a) Chip-loss
max(h, 0)
ψ_e(h)
χ_e(h)
Effective thickness [mm]
Chip thickness h [mm]
(b) Engagement
g_i(θ)
[a_{i,r,k}, b_{i,r,k}]
θ_entry
θ_exit
Spindle phase θ [rad]
(c) Quadrature
midpoint samples
Force integrand
K_a ψ_e + K_ae χ_e
Phase variable ϑ [rad]