AVIATION INVESTIGATION

Alaska Airlines Flight 1282

Three dates mark the incident, the regulator's immediate response and the safety board's later finding.

05 JAN 2024

Incident

A door plug separated in flight. The aircraft returned to Portland.

NTSB investigation record

06 JAN 2024

Grounding order

The FAA temporarily grounded certain Boeing 737-9 MAX aircraft.

FAA grounding updates

24 JUN 2025

Probable cause

The NTSB announced its probable-cause finding for the door plug separation.

NTSB board findings

Read the record in order

The grounding order describes an immediate safety action. The later finding comes from the NTSB investigation.

Full timeline and sources