FLEET TEAM DIGEST

737MAX-FTD-00-24001

Issue Title : 737MAX AIPC Part Entry Change Notifications

Airplane Model	ATA	Minor Model(s)
737MAX	0000-61	-10, -8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
02/01/2024	08/10/2026	08/10/2026
Estimated Completion Date	**Next Update Date**	
11/28/2030	12/31/2026	

Revision Description

This release includes information pertaining to a Latch Assy and a Parking Brake Shutoff Valve Assy

Description

Operators of Boeing aircraft have previously experienced disruptions due to the removal of parts or part effectivity from the Aircraft Illustrated Parts Catalog (AIPC) without prior notification. Operators have requested that Boeing provide advance notification of such removals from the AIPC. The intent of this FTD article is to provide awareness of the limitation or removal of parts or part effectivity from the AIPC.

Boeing Spares Engineering and AIPC teams have established a collaborative process to inform operators when changes in the Spares Technical Engineering Process System (STEPS) will result in the limitation or removal of parts or part effectivity in an upcoming publication of the AIPC. This FTD article will be used to deliver the AIPC change information in an attachment. The attachment includes details such as the part numbers involved, the affected aircraft, and the expected AIPC publication date for the changes. Information from previous FTD article releases will be available in the 'Historical' tab in the attachment. This FTD article will be updated and released when STEPS changes evaluated by the AIPC team are determined to have a critical impact to the 737MAX fleet.

Status

Please see attachment *737MAX_AIPC_Change_Summary* for additional details.

Interim Action

Please review the changes identified in the attachment for potential impacts to your fleet. If there are any questions regarding the content of the attachment, please submit an inquiry to AIPC Customer Support team in the Boeing Communication System (BCS). In BCS, select '*Drawings, Data & Maintenance*' for the Service Category; '*Maint. and Repair Document*' for the Product Type; '*737*' for the Product Line; and '*IPC (737-7/8/8200/9) Aircraft Illustrated Parts Catalog*' for the Product.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

Confirm the impacts to your fleet. If part replacement is required and additional guidance is needed beyond what will be supported in the AIPC following the changes detailed in the attachment, please contact the Service Engineering team via BCS by selecting '*Airplane Repair*' for the Service Category.

Milestones

This FTD article will be updated and released when STEPS changes evaluated by the AIPC team are determined to have a critical impact to the 737MAX fleet.

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

Attachments:

a) 737MAX_AIPC_Change_Summary Rev 12

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991