FLEET TEAM DIGEST

737MAX-FTD-05-18001

Issue Title : 737 MAX Structural Airworthiness Limitations (AWLs)

Airplane Model	ATA	Minor Model(s)
737MAX	0500-00	-7, -8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
10/26/2018	08/16/2022	07/12/2022
Estimated Completion Date	**Next Update Date**	

Revision Description

This update reinstates the Temporary Operation Limit (TOL) for 737-7 airplanes. All tasks are completed and this article is now closed.

Applicability

All 737 MAX airplanes

Description

Boeing has received service requests from operators as to when all the 737 MAX inspection data would be made available supporting removal of the Temporary Operational Limitation in the AWL.

Background

As reflected in the referenced Airworthiness Limitations (AWLs) D626A011-9-01 document, the Temporary Operational Limitation (TOL) for each aircraft is “4 years or 15,000 total flight cycles from aircraft delivery, whichever comes first”. For aircraft modified with Boeing Service Bulletin 737-21-1217, the TOL is “4 years or 5,000 total flight cycles from aircraft delivery”. Once the damage tolerance based inspections, including thresholds and repeat inspections, are completed, and published in the AWL, the Temporary Operational Limitation will be removed.

Status

Required inspections for ATA 52 (Doors) and ATA 55 (Empennage) are currently published. Refer to titled “Airworthiness Limitations (AWLs) D626A011-9-01”.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Airworthiness Limitations (AWLs) D626A011-9-01 and D626A010 published 01-Jan-2021 reflects the following:

- Removed the initial TOLs for 737-7/8/8200 since the DTRs are completed for these airplanes.

Airworthiness Limitations (AWLs) D626A011-9-01 and D626A010 published 01-Feb-2022 reflects the following:

- Due to Amended Type Certificate (ATC) changes for the 737-7 airplane, Boeing has temporarily reinstated the TOL for this airplane.

Boeing created MOM-MOM-21-0532-01B to inform operators of the changes to the AWL and DTR documents and is posted/ available in the New Performance Tool on MyBoeingFleet.

Interim Action

None.

Final Action

737-7/8/8200/9 AWL (D626A011-9-01) and DTR (D626A010) updated to include ATA 53 (Fuselage) and the remainder of the ATA 57 (Wings) required inspections. The TOL was removed from the AWL for airplane models 737-7/8/8200 in the January 2021 revision. The TOL for some inspections for the 737-9 was removed in April 2021. The TOL for the reinstatement of the 737-7 airplanes has been completed.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Airworthiness Limitations (AWLs) D626A011-9-01 and D626A010 Available: 01-Jan-2021 (complete)

Additional inspections for ATA 53 (Fuselage), ATA 54 (Pylons), and ATA 57 (Wings) Available: 2Q2021 (complete)

TOL for 737-9 removed: April 2021 (complete)

TOL for 737-7 reinstated: 01-Feb-2022 (complete)

MOM-MOM-21-0532-01B available: 22-Nov-2021 (complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Multi-Operator Message (MOM)	MOM-MOM-21-0532-01B		11/22/2021
Maintenance Planning Document (MPD)	D626A001, Section 2		
Other	- Damage Tolerance Rating (DTR) D626A010		02/01/2018
Service Bulletin (SB)	737-21-1217	01	07/17/2018
Other	- Airworthiness Limitations (AWLs) D626A011-9-01		01/01/2021

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991