FLEET TEAM DIGEST

737MAX-FTD-21-26002

Issue Title : Hot Cabin Working Together Team (WTT) Best Practices

Airplane Model	ATA	Minor Model(s)
737MAX	2123-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
07/07/2026	10/07/2026	07/20/2026

Estimated Completion Date	Next Update Date
01/29/2027	01/29/2027

Revision Description

Revising article to add Hot Cabin Best Practices attachment.

Applicability

All 737 MAX Airplanes.

Description

Hot Cabin Working Together Team (WTT) is a Boeing Customer Support Initiative that provides a forum for collaboration between 737NG/MAX Operators, Boeing, and Suppliers with the goal of developing improvements/best practices to mitigate Hot Cabin events.

This initiative engages operators and Boeing to:

- Provide a venue for operators to share knowledge/experiences and offer solutions/recommendations that could potentially help the fleet, and/or allow Boeing to identify areas of improvement.
- Jointly investigate problems and assist in identifying next steps.

Background

The Hot Cabin WTT arose from feedback surrounding the need for maintenance and operational best practices, a forum for troubleshooting discussions, and a method to receive updates related to investigations and potential future solutions related to Hot Cabin events experienced at airlines during their fleet operations. This Fleet Team Digest (FTD) article will be updated periodically to communicate progress and accomplishments related to Hot Cabin WTT initiatives and projects.

Status

The Hot Cabin WTT meets twice a year as part of the Environment Control Systems (ECS) WTT to discuss any action items taken at the last meeting, the open/in-work projects/investigations, recent releases related to Hot Cabin, and any updates on in-work projects or projects under consideration.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The last meeting occurred on May 12, 2026 during the 737 Fleet Team Meeting in Huntington Beach, CA. The meeting materials are available in the attachments section of this FTD Article. Accomplishments include:

- ATA 36 Fault Isolation Manual (FIM) Update (improved troubleshooting for bleed air system; see 737NG-FTD-36-11002 for details) released OCT 2024
- Heat exchanger clearing (compressed air) training video released to MyBoeingFleet in MAR 2025
- ATA 21 Aircraft Maintenance Manual (AMM)/FIM Update published JUN 2025 737NG / SEPT 2025 737 MAX
  - Improved air conditioning and air distribution system maintenance & troubleshooting
- 737-SL-21-108-B revision for pack maintenance best practices released AUG 2025
  - Predictive Monitoring Charts for air conditioning pack systems and maintenance guideline for pack/distribution components
- 2 & 3 Nozzle Configuration Heavy Check Orifice Cleaning AMM Update released FEB 2026
  - Clarified procedures for 737NG and added new AMM task for 737 MAX
- Honeywell Heat Exchanger Component Maintenance Manual (CMM) Update (to improve verification of HX cleaning) published APR 2026
- Flight Operations Technical Bulletin (FOTB) 26-04 Cabin Temperature Control During Ground Operations in Hot Weather published APR 2026

Interim Action

Best Practice Recommendations are as follows:

1. Follow the latest released revisions of ATA 21/36 Boeing AMM/FIM procedures mentioned in the "Status" section
2. Follow FCOM Procedures; paying special attention to all warnings and cautions*
   a. On the 737 MAX, to improve cabin air temperature between starting the first and second engine, Boeing recommends utilizing FCOM SP "Isolated Pack Operation during Engine Start"
   b. Reference FOTB 26-04 and FCOM SP "Hot Weather Operation" for additional guidance on ground operations during hot weather operations
   c. When utilizing a ground conditioned air cart, follow the warnings and cautions listed in the FCOM SP "Ground Conditioned Air Use" and the associated AMM procedures and ensure that the air conditioning packs and the ground conditioned air cart are not operated at the same time. Operating the packs and the ground conditioned air cart at the same time can lead to damage of the pack/air distribution system hardware.
3. Follow Best Practice Documentation outlined in 737-SL-21-108 and referenced by the Operational Efficiency Dashboard (access instructions attached)
4. For Heat Exchanger Cleaning and Tooling information, refer to 737NG-FTD-21-16005

Boeing recommends airline customers attend recurring WTT engagements and provide feedback at the WTT meetings or via the Fleet Idea Exchange Post ISE-21-26-52756.

Final Action

Not Applicable, this FTD is for reference only.

Milestones

Not Applicable

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article	737NG-FTD-36-11002		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

(FTD)			
Flight Crew Operating Manual (FCOM)	737 MAX FCOM Supplementary Procedure "Hot Weather Operation"		05/31/2026
Flight Operations Technical Bulletin (FOTB)	737 26-04 Cabin Temperature Control During Ground Operations		
Flight Crew Operating Manual (FCOM)	737 MAX SP "Isolated Pack Operation during Engine Start"		
Fleet Team Digest Article (FTD)	737NG-FTD-21-16005		
Fault Isolation Manual (FIM)	ATA 36 and ATA 21		
Aircraft Maintenance Manual (AMM)	ATA 21		
Component Maintenance Manual (CMM)	Honeywell HX CMM (21-50-14)		
Flight Crew Operating Manual (FCOM)	737NG FCOM Supplementary Procedure "Hot Weather Operation"		09/30/2026
Service Letter (SL)	737-SL-21-108		
Other	Operational Efficiency Dashboard		

Related Categories

- Aging Airplane Issues : Structural issues or systems wear due to high flight cycles or high flight hours on the airplane
- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.

Attachments:

a) Hot Cabin Best Practices Aug-2026

b) Hot Cabin WTT Presentation - 737 FTM May 2026

c) How To Access Operational Efficiency Dashboard

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991