FLEET TEAM DIGEST

737MAX-FTD-23-25001

Issue Title : Emergency Locator Transmitter (ELT) Obsolescence-

Airplane Model	ATA	Minor Model(s)
737MAX	2324-00	-10, -7, -8, -8200, -9

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
11/26/2025	04/07/2026	02/17/2026

Estimated Completion Date	Next Update Date
12/31/2026	05/15/2026

Revision Description

Updated Status section to show TSO certification sliding to 4Q 2026. Updated Interim Action section to add a note indicating S-Batteries requiring a battery only check and not replacement. Added the following attachments to the FTD; P-ELT Buyback Letter (Feb'26), HON (Honeywell) Call to Action Letter (Feb'26),

Description

ELT supplier Honeywell has identified an obsolescence issue regarding sub-components that are part of the Radio Frequency (RF) module used in both their current fixed ELT model 406AFN2 (part number: 51090414-1) and portable ELT model 406SG (part number: 51090368-1). Due to the parts obsolescence, the current number of available RF modules used in ELT production will be limited.

In order to address the obsolescence, Honeywell has begun a redesign of the RF module that replaces the obsolete parts for a long-term solution to obsolescence.

Until the redesigned RF module is available, there exists a potential gap in the availability of RF modules used to manufacture current model fixed and portable Honeywell ELTs. Both Honeywell and Boeing are working to ensure there will be enough Honeywell ELTs available until ELTs with the redesigned RF module are available.

Status

Honeywell's ELT product line is in the process of being transitioned to Dukane Seacom (Dukane). There have been multiple challenges over the past two years since Honeywell announced the transition of the ELT product line to Dukane Seacom (Dukane). Honeywell and Dukane have worked closely together to overcome yield issues and continue to work together through current challenges with the limited quantity of RF Modules remaining from the last time purchase due to obsolescence.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Due to RFmodule parts obsolescence and subsequent RF module redesign, there is a limited quantity of RF modules available for current Fixed ELT (F-ELT) model 406AFN2 and Portable ELT (P-ELT) model 406SG production. As a result, the supply of modules is being tightly controlled by Dukane Seacom (Dukane).

Dukane and Honeywell are working to complete the redesign of the RF Module and current estimation for TSO certification is 4Q-2026.

Interim Action

Report Legacy ELTs (PN starts with 115-) battery expirations to Dukane:

- Battery Expiration Date - The date printed on the exterior label of the Honeywell ELT unit is the month and year of the battery expiration and the ELT battery is valid through the last day of the month and year on the label. For example, 10/2025 represents the ELT battery is valid thru Oct 31, 2025.
  - Email expiration data to Dukane: Danielle Sladky - dsladky@rpcaero.com and Tyler Needham - tneedham@rpcaero.com
  - Include:
    - PN (starts with 115-)
    - SN
    - Tail #
    - Battery Expiration date

Raise AOG orders within 14 days of expiration for Legacy ELTs (PN starts with 115-) to Honeywell:

- Expiring Legacy AFN/SE ELTs - Part numbers for these units all begin with 115 as the first three digits (Examples: 1152682-1, 1153426-1M900, Etc.). These units are not eligible for battery replacements and require replacement of the ELT.
  - Contact Honeywell AOG Desk: AOG@honeywell.com
    - Due to the limited quantity of units until RF Module redesign is complete, only verified AOG orders are currently being accepted to mitigate the risk of grounded aircraft until redesign is completed.
    - Note: S-Batteries (which start with PN: 115) require a battery only check and not replacement.

Replace battery packs for Current ELT (PN starts with 510-) through Turner Aviation, do not replace with full unit assemblies:

- Expiring AFN2/SG models - Part numbers for these units are: 51090414-1 and 51090368-1. These units DO NOT need to be replaced as batteries (PN: 51080200-1) are available from Honeywell for customers with capabilities to complete in house.
  - Order Battery Pack: Honeywell
  - Battery replacement, repair and testing services: Turner Aviation (MRO)

F-ELT Buyback Program (PN: 51090414-1): Available for operators retrofitting a fixed ELT off Boeing aircraft to install a GADSS compliant distress-tracking ELT. Contact Dukane Seacom (Dukane) Danielle Sladky (dsladky@rpcaero.com) and Tyler Needham (tneedham@rpcaero.com) for more details and stocking levels.

Final Action

Completion of the RF module redesign and availability of new redesigned fixed and portable ELTs.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Milestones

An update to provide milestones and schedule will be provided in a future revision of this FTD in 3Q2026.

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Obsolescence : Information on parts that are obsolete, becoming obsolete, or have excessive lead times

Attachments:

a) MOM-MOM-25-0269-01B-

b) Fixed ELT Retrofit for GADSS Program Letter-

c) Portable ELT Buyback Program Letter

d) HON Call to Action Letter

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991