FLEET TEAM DIGEST

737MAX-FTD-34-19004

Issue Title : 737 Flight Management Computer - In Service Fault Analysis

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
02/22/2019	02/22/2019	02/22/2019

Estimated Completion Date	Next Update Date

Applicability

All 737MAX Airplanes

Description

This FTD is intended to provide operators with information requested to support Flight Management fault reports, which will assist follow up investigation into reported FMC in-service issues.

Background

Boeing has seen FMC LRUs removed unnecessarily, such as removal for faults associated with software. In some cases, additional information from operators is required to support follow up investigations of reported in-service issues.

Status

This FTD can be used to assist operators in reporting FMC in-service issues and related data to support follow on investigation.

Interim Action

No Interim Action required.

Final Action

To support any follow up investigation of FMC in-service events, please provide as much information as possible as noted on the attachment to this Fleet Team Digest article.

Operator Action

Operators are encouraged to use available AMM resources to identify FMC software (s/w) related faults that do not require removal of the FMC.

The Boeing Interactive FIM for FMC Fault Maintenance Messages, 34-61001 and 34-61002 has been updated to differentiate between hardware and software type faults. LRUs should not be removed for faults associated with software.

For chronic faults, operators are encouraged to provide FMC Fault Log data per the FMC Diagnostic Data Transfer procedure,

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

AMM TASK 34-61-00-810-801/TASK 34-61-00-810-802.

For Dual FMC installations, the fault log from both the left and right FMC should be collected. The data can be collected into a zip file and e-mailed directly to GE at:

737fmchelp@ge.com

Please indicate the customer name and airplane number along with the data.

In addition to the FMC Fault Log, it is always helpful to provide as much information as practical to assist follow up investigation and attempts to reproduce any reported condition.

The attachment to this FTD provides guidelines related to the information that can be used to assist follow up investigation of reported FMC in-service issues.

Additional information regarding FMC maintenance can be found in GE Aviation Supplier Service Letter, 34-49.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Information Letter (SIL)	GE Aviation 34-49 FMC Maintenance Guidelines		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Flight Management Comuter	10-62225-004	GE Aviation	176200-01-01

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

Attachments:

a) FMC In Service Issue Data Sheet

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991