# FLEET TEAM DIGEST

## 737MAX-FTD-31-23002

**Issue Title :** Max Display System Software BlockPoint 2 Status

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3165-00 | -10, -7, -8, -8200, -9 |
| **Other Model(s)** | **ECCN** | |
| | 9E991 | |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 04/13/2023 | 08/14/2026 | 06/01/2026 |
| **Estimated Completion Date** | **Next Update Date** | |
| 12/23/2026 | 09/30/2026 | |

## Revision Description

A new Operator Action has been defined. Two related PRRs and one related FTD have been added to the references. A new Milestone has been added.

## Applicability

All 737MAX Airplanes

## Description

Following multiple inquiries regarding 737 MAX Display System (MDS) Software BlockPoint (BP) 2, Boeing is publishing this Fleet Team Digest (FTD) for tracking the development of MDS BP2.

This is an umbrella publication outlining the status of MDS BP2 relating to the following FTDs:

1. 737MAX-FTD-27-18002
2. 737MAX-FTD-31-18004
3. 737MAX-FTD-31-18005
4. 737MAX-FTD-31-19001
5. 737MAX-FTD-31-21005
6. 737MAX-FTD-31-23004
7. 737MAX-FTD-31-24003
8. 737MAX-FTD-49-18001
9. 737MAX-FTD-77-18003
10. 737MAX-FTD-80-18001

## Status

MDS BP2 software (SW) is targeted to be certified by the 3Q 2026. Subsequently, Boeing will be making this SW available via Service Bulletin.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Interim Action

None.

## Final Action

When available, Boeing recommends operators to incorporate Max Displays System (MDS) BlockPoint (BP) 2 Release, MDS BP 2, via Service Bulletin 737-31-1929.

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: N/A
Solution Selected: N/A
Production Incorporation: Concurrent to 737-10 ATC [Q3 2026 (target)]
Service Bulletin: Service Bulletin 737-31-1929 will be available subsequent to Production Incorporation [Q4 2026 (target)]
Service Bulletin 737-34-3806 See FTD 737MAX-FTD-27-23003

## Operator Action

In order for in-service airplanes to access new features provided by MDS BP2, the existing Option Selection Software (OSS) part number will need to be updated with a new part number. There are two new options/features that need to be defined. This new MDS OSS will be made available via the Enhanced Angle of Attack (eAOA) Service Bulletin 737-34-3806.

Option/Feature OSS_ND_ARPT_MAP_ENABLED (3162F589A22) enables the Airport Map function on the Navigation Display (ND) and enables the Airport Map Database selection on the INFO page.

Note: If operators choose to enable this option, a subscription with Jeppesen for the Airport Map Database (AMAP DB) is required. (PRR 3M0279-2)

Option/Feature OSS_ND_TIME_ALIGN_PPOS enables the display of the time remaining to align both Left and Right IRUs and the Present Position on the ND. Operators can choose to retain the ISDU and keep this option disabled. (PRR 3M0178)

For operators planning to update their in-service airplanes according to the timeline of SB 737-34-3806, Boeing requests operators to submit the following information to Boeing via Boeing Communication System (BCS) Service Request (SR) under ATA 31 by 30-SEP-2026 (if time of reading is prior to this date) or as soon as possible.

- Boeing requests operators to confirm if the two options above should be enabled or disabled for each effective airplane in the in-service fleet.

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Fleet Team Digest Article (FTD) | 737MAX-FTD-27-23003 | | |

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

| | | | |
|---|---|---|---|
| Fleet Team Digest Article (FTD) | 737MAX-FTD-27-18002 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-18005 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-19001 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-21005 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-49-18001 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-77-18003 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-80-18001 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-18004 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-23004 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-24003 | | |
| Production Revision Record (PRR) | 3M0279-2 | | |
| Production Revision Record (PRR) | 3M0178 | | |

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991