FLEET TEAM DIGEST

737MAX-FTD-28-25001

Issue Title : Fuel Tank Penetration Bond Degradation_

Airplane Model	ATA	Minor Model(s)
737MAX	2822-00	-10, -7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
05/30/2025	08/12/2026	05/27/2026
Estimated Completion Date	**Next Update Date**	
06/30/2028	08/28/2026	

Revision Description

Updated Milestones section.

Description

Potential degradation of electrical faying surface bonds at engine fuel-feed, tank-penetrating fittings may cause electrical resistance values to exceed design limits. These bonds serve to limit lightning conducted current into the fuel tank and therefore a compromised bond increases the potential for electrical sparking in the fuel tank, potentially leading to fuel tank ignition.

Status

The FAA has reviewed and determined this condition to be "airplane safety."

Boeing's safety determination is that 737 MAX is “out of scope” because it has smaller jam nut than NG, higher torque value and zero net loading at the fuel fitting or fuel tubing (fuel penetration). Engineering Validation Testing (EVT) monitoring program will occur starting in Q4 2026 and this model will be brought back to the Boeing safety board if results show resistance values beyond the acceptable range.

A Service Related Problem (SRP) 737MAX-SRP-28-0066 was initiated nonetheless on 30-Jan-2025 to address this potential issue. Boeing Subject Matter Experts are currently working to determine appropriate technical solutions as applicable.

Interim Action

To be determined.

Final Action

Final actions are pending resolution through the SRP project.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

SRP Opened: January 2025 (Complete)

Root Cause Established: 05-Dec-2025 (Complete)

Solution Selected: Q3 2026 (target)

Production Incorporation: Q2 2028 (target)

Service Bulletin Available: Q2 2028 (target)

Related Categories

- Aging Airplane Issues : Structural issues or systems wear due to high flight cycles or high flight hours on the airplane
- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991