

SERVICE REPORT

Technical Field Services Division

#v(2pt) Report ID:) #SR-99421

~~#line(length: 100%,stroke: 0.5pt +~~
~~rgb("#A0AEC0")) #v(-2pt) Technician~~

```
#line(length: 100%,stroke: 0.5pt
rgb("#A0AEC0")) #v(-2pt) Client
```

Signature: 0%, stroke: 0.5pt + Client: Midwest Manufacturing Inc.
rgb("#A0AEC0") #v(-2pt) west Manufacturing Inc. David
Miller ture: 0%, stroke: 0.5pt + Site
Location: acturing Inc. Plant #3 - 1400
rgb("#A0AEC0") #v(-2pt) Industrial Pkwy, Gary, IN
nt #3 - 1400 Industrial Pkwy, Gary, IN
Contact: 3 - 1400 Industrial Pkwy, Gary, IN
Robert Vance (Maintenance Mgr) Gary, IN

Sign-Off: h: 100%,stroke: 0.5pt +
Date of Service: July 28, 2026:
 y 28, 2026: **Technician:** 026 : David Miller
 Vance, h: 100%,stroke: 0.5pt +
 (Tech ID: 8042)
 id Miller (Tech ID: 8042) **Asset/ Serial ID:** h
ID: 8042) CNC-Milling Unit #04 (SN: 883-9021)

1. WorkPerformed & Findings

Performed emergency diagnostic on main drive motor overheating issue. Replaced degraded thermal coupling, flushed cooling lines, and updated firmware to v4.2.1. System recalibrated and load-tested for 45 minutes under nominal factory conditions with zero thermal warnings.

2. Parts & Materials Used

Part #	Description	Qty	Status
TC-9042	High-TempThermal Coupling	1	Replaced
CL-1020	Synthetic Coolant Fluid (1L)	2	Consumed
FW-4200	Firmware Update Flash Memory	1	Installed

3. Job Status & Follow-Up

```
rect(fill:      rgb("#FEFCBF"  
, width: 100%,inset: 8pt, radius: 3pt, stroke: 0.5pt + rgb(""  
"))[  
Job Status: Completed/ Operable  
],  
rect(fill:      rgb(""  
"), width: 100%,inset: 8pt, radius: 3pt)[  
Action Required: Routine inspection recommended in 90 days.  
]  
)
```