
Run 1
Run 2
Run 3
Run 1 + 2
Run 2 + 3
Run 1 + 3
0.0
0.5
1.0
1.5
Surface distance (mm)
RMS, calibration
RMS, excluded run
Scan→model p95
Model→scan p95