

Inspection Report - Machine ID: MC-1042

Inspection Date: 2026-08-20 Inspector: J. Alvarez

Findings Summary

Checklist Item	Status	Remark
Bearing vibration level	FAIL	Vibration exceeds threshold (7.2 mm/s vs 4.5 limit)
Oil level check	PASS	Within specified range
Coupling alignment	FAIL	Misalignment detected, offset 0.9 mm
Coolant temperature	PASS	Within tolerance
Belt tension	FAIL	Tension below minimum, needs retightening

Recommended action: Perform corrective maintenance and re-inspect.