
IDLE
C↑ ∨ F
/ change_active+ = true, change_done+ = false
arr>0.5
/ change_done+ = true, change_active+ = false
MOVING_TO_WIPE
motors on, extruder off
r = (xw, yw)
READY_TO_RESUME
motors on, extruder off
r = (xs, ys)
arr>0.5
heated ∧ paused
WIPING
motors on, extruder on
r = (xw + 0.02, yw)
NOZZLE_HEATING
extruder off
τ ≥ tw
/ req+ = false
τ ≥ tl
/ req+ = true
NOZZLE_COOLING
extruder off
¬heated
LOADING_FILAMENT