
IDLE
motors off, extruder off
r = (0, 0)
IN_PROGRESS
START
/ req+ = true
WAIT_HOT
motors off, extruder off
heated
TRAVEL_TO_START
motors on, extruder off
r = path(max(k−1, 1))
arr>0.5
/ k+ = max(k, 2)
PRINT_PATH
motors on, extruder on
r = path(k)
k < n ∧ arr
/ k+ = k + 1
k = n ∧ arr>0.5
/ req+ = false
COMPLETED
motors off, extruder off
change_done ∧
¬change_active
/ paused+ = false, req+ = true
C↑ ∨ F
/ paused+ = true, req+ = false,
(xs+, ys+) = (x, y)
PAUSED
motors on, extruder off
r = (xs, ys)