
IDLE
hasChangedTo(C, 1) || F
MOVING TO WIPE
duration(arrived)>0.5
WIPING
after(p.t_wipe,sec)
NOZZLE COOLING
~heated
LOADING FILAMENT
after(p.t_load,sec)
NOZZLE HEATING
heated && ~paused
heated && paused
READY TO RESUME
duration(arrived)>0.5