
IDLE
MOVING TO WIPE
WIPING
NOZZLE COOLING
LOADING FILAMENT
NOZZLE HEATING
READY TO RESUME
hasChangedTo(C, 1) || F
duration(arrived)>0.5
after(p.t_wipe,sec)
~heated
after(p.t_load,sec)
heated && ~paused
heated && paused
duration(arrived)>0.5