

ERROR MEMORY REPORT

Date: 09/09/26 10:42:12
ECU: DSC57
JobStatus: OKAY
Variant: DSC57

RESULT: 3 errors in error memory !

5 wheel speed sensor rear right plausibility

Error frequency : 255

Vehicle speed 30.94 km/h

ASC not passiv
ABS-control passiv
stop light switch off
ASC-control passiv
ACB passive
HBA passive
ECD passive
HDC passive

90 temporary system deactivation

Error frequency : 227

Vehicle speed 2.38 km/h

ASC not passiv
ABS-control passiv
stop light switch off
ASC-control passiv
ACB passive
HBA passive
ECD passive
HDC passive

108 SN-control

Error frequency : 233

Vehicle speed 2.75 km/h

ASC not passiv
ABS-control passiv
stop light switch on
ASC-control passiv
ACB passive
HBA passive
ECD passive
HDC passive

=====