



Summit Hood Service Co.
Austin, TX | 24/7 dispatch

PDF COPY

Sample Restaurant Group

Reachable work was completed. The blocked area is listed separately and is not presented as cleaned. Attached photos support only the areas shown.

PDF copy	✓ Action item visible
Service date	Apr 24, 2026
Location	Austin, TX
System	Main cookline hood line
Today's result	Completed with open access exception
Report ID	HDS-SAMPLE-0424
Record basis	Partial photos
Record type	Access Issue Record
Record support	Partial photo record
Photo coverage	3 photo areas attached
What this service covered	Completed work and blocked access stay separated, so the customer can see what was reachable and what still needs action.
Customer next step	Reply after clearing access

DIRECT LINE	DISPATCH	CREDENTIAL	AFTER-HOURS
(512) 555-0148	dispatch@summit.example	TX Reg #KEX-2087	(512) 555-0192

Excluded area listed

Service report for customer files.

Prepared for customer files, manager review, landlord, insurance, or documentation requests. It identifies the property, service provider, service date, completed areas, excluded areas, photo status, label details, and retained-copy trail.

Record type	Kitchen exhaust service report PDF copy
Report ID	HDS-SAMPLE-0424
Customer / property	Sample Restaurant Group
Service location	Austin, TX
System reference	SYS-01 / Main cookline hood line
Line served	Main cookline hood line
Service date / window	Apr 24, 2026 01:10-03:05
Service provider	Summit Hood Service Co.
Person performing work	Miguel R. / Tech ID SH-114
Service result	Completed with documented exception
Record basis	Service record with attached field photos

REPORT SHEET FIELDS

Component status, exclusions, and retained evidence are separated.

Document class	Customer-retained service report copy
Service outcome	Completed with excluded area listed
Hood / filters	Cleaned - Work recorded for this section.
Duct / access status	Reachable cleaned - Accessible path cleaned; rear access remains blocked.
Rooftop fan status	Documented - Fan housing, hinge/base, curb, and roof discharge condition recorded for customer file.
Grease path status	Documented - Grease trough, drip path, removed buildup, and containment condition recorded for customer file.
Areas completed / cleaned	Hood canopy interior, Baffle filters / tracks, Plenum / reachable duct path
Recorded only	Fan / roof discharge, Grease trough / containment path
Blocked / inaccessible area recorded	Yes - see excluded area
Reachable service path	Accessible sections completed; excluded area listed separately
Deficiencies / exceptions	Stored equipment blocked full access at service time.
Areas not cleaned / excluded	Rear duct access panel
Before / after photo evidence	Included - 3 photos
Service label / notice	EXC-0424-DK02
Record maintained on premises	Customer to retain with kitchen exhaust service records
Service provider copy	Customer copy and service provider archive retained
Recommended interval	90-day cycle
Next service window	Jul 18-23, 2026
Reviewer note	Manager, landlord, insurer, or AHJ may apply separate requirements

TECHNICIAN

Miguel R. / Tech ID SH-114

COMPANY CREDENTIAL

TX Reg #KEX-2087

PREPARED BY / SIGNATURE

RECORD COMPLETENESS CHECK

IDENTITY

Provider, worker, customer,
location, system, date, report
ID

AREAS

Hood, filters, duct/access,
fan, grease path, excluded
areas

EVIDENCE

Photo status, component
status, label ref, retained
archive

BOUNDARY

Separate from corrective
work and outside reviewer
requirements

DOCUMENT CONTROL

Record identifiers and retained copies.

Report ID	HDS-SAMPLE-0424
Document title	Kitchen exhaust service report
Prepared date	Apr 24, 2026
Service date / window	Apr 24, 2026 01:10-03:05
Servicing company	Summit Hood Service Co.
Person performing work	Miguel R. / Tech ID SH-114
System reference	SYS-01 / Main cookline hood line
Service provider archive	Retained
Customer copy	PDF service report copy
Photo archive	Retained by service provider
Service label / sticker ref	EXC-0424-DK02

SUBMISSION USE

What this record can and cannot support.

Use for	Customer records; manager review; landlord, insurance, or documentation requests
Does not authorize	Separate corrective or follow-up work
Reviewer boundary	Manager, landlord, insurer, or AHJ may apply separate requirements
Record source	Service facts, route status, and attached photos recorded by the service provider
Area limit	Blocked or inaccessible areas are excluded until access is provided
Premises copy	Maintain this record with kitchen exhaust service records

EXCLUDED AREAS

Any area outside completed work.

Area	DK-02 Rear duct access panel
------	------------------------------

CUSTOMER / PROPERTY FIELDS

Fields used for outside record requests.

Customer / property	Sample Restaurant Group
Service location	Austin, TX
System	SYS-01 / Main cookline hood line
Line / area served	Main cookline hood line

SERVICE LABEL / STICKER

Field label details tied to the service record.

Label / sticker reference	EXC-0424-DK02
Label status	Yes - service date + report reference
Posted location	Kitchen area / serviced hood system
Date cleaned	Apr 24, 2026
Next due	Jul 23, 2026

SERVICE AREAS

What was handled, what stayed open.

Use this list to see which parts of the exhaust system were cleaned, documented, or left for follow-up.

Hood canopy interior	Work recorded for this section.	Cleaned
PARTIAL: P-02		
Baffle filters / tracks	Filters removed, cleaned, checked, and reinstalled; tracks and nearby grease collection points documented where accessible.	Removed + reset
P-03		
Plenum / reachable duct path	Accessible path cleaned; rear access remains blocked.	Reachable cleaned
P-04		
Rear duct access panel	Stored items blocked access; not represented as cleaned.	Access blocked
P-04		
Fan / roof discharge	Fan housing, hinge/base, curb, and roof discharge condition recorded for customer file.	Documented
SERVICE RECORD		
Grease trough / containment path	Grease trough, drip path, removed buildup, and containment condition recorded for customer file.	Documented
SERVICE RECORD		

PHOTO EVIDENCE

Photo evidence attached.

Hood before	P-01	Not captured
Hood after	P-02	Captured
Filter bank / tracks	P-03	Captured
Access condition	P-04	Captured
Rooftop fan	P-05	Not captured
Grease path / containment	P-06	Not captured
Service label / notice	P-07	Not captured

FREQUENCY BASIS

Cooking line type	Main Type I cookline
Observed grease load	Moderate to heavy
Operating pattern	High-volume dinner service
Recommended interval	90-day cycle
Next service window	Jul 18-23, 2026
Interval note	Current grease load and line volume support a 90-day cycle.

PHOTO EVIDENCE


Photos are organized as evidence.

Customer sees the service result, attached photos, next action, and a clear PDF copy in one branded service report link.

What you are seeing

This record shows the selected service result and only the attached field photos. Uncaptured areas stay listed as not captured or record-only.

What stays in service records	Raw field photos, technician notes, and the PDF copy stay available for archive, submission, or print copy.
Action items	Reachable sections were completed. The blocked section stays listed separately until access is cleared.
Record type	Access Issue Record
Record source	Vendor-confirmed access issue with service closeout details. The selected result includes a blocked or inaccessible area, so the customer action stays primary.
Evidence note	Attached photos support only the areas shown. Other service areas remain documented by written service notes.
Claim limits	Attached photos support part of the record; areas not photographed stay listed by record basis. Inaccessible areas are listed separately and are not presented as cleaned.
Action boundary	Reachable sections were completed. The blocked section stays listed separately until access is cleared.
Photo coverage	3 photo areas attached
What this service covered	Completed work and blocked access stay separated, so the customer can see what was reachable and what still needs action.
Customer next step	Reply after clearing access
Hood before	Before hood photo is not attached to this record.
Rooftop fan	Rooftop fan photo is not attached to this record.
Grease path / containment	Grease path / containment photo is not attached to this record.
Service label / notice	Service label / notice photo is not attached to this record.



Hood interior after clean

Field photo captured after reachable surfaces were cleaned. Local field photo: sample-hood-after.jpg.

AFTER CLEAN CONFIRMATION



Duct access condition

Access, blocked section, or exception condition tied to the report.
Local field photo: sample-access-condition.jpg.

ACCESS-PATH RECORD

SERVICE LABEL AND CONTACT



Signoff details stay attached.

Service label type	Access exception notice
Label / notice ref	EXC-0424-DK02
Label posted	Yes - service date + report reference
Reviewed on site	Store manager
Record retention	Customer copy and service provider archive retained
Next due	Jul 23, 2026
Prepared by technician	Summit Hood Service Co. SH-114
Technician credential	TX Reg #KEX-2087
Dispatch	dispatch@summit.example
Delivery record	Service report link sent; PDF copy available

NOT INCLUDED IN THIS SERVICE REPORT

This service record covers this kitchen exhaust cleaning visit for one exhaust system. separate corrective or follow-up work are not included unless separately quoted. Attached photos support part of the record; areas not photographed stay listed by record basis. Inaccessible areas are listed separately and are not presented as cleaned.

CUSTOMER FILE NOTE

Customer copy retained with the service report record.

Site contact	Store manager / masked
Customer action	Clear rear access and reply
Record location	Keep with kitchen exhaust service records