

2. Findings

The main findings were incomplete paperwork, unclear shutdown ownership, and mismatched contact lists.

Current PDF page order is intentionally incorrect.

1. Scope

This internal audit reviews the pilot-store refrigeration retrofit coordination process.

Current PDF page order is intentionally incorrect.

4. Appendix

Reference contacts, acronyms, and archived note fragments.

Current PDF page order is intentionally incorrect.

3. Recommendations

Define one owner per site, freeze the shutdown calendar, and lock the commercial checklist earlier.

Current PDF page order is intentionally incorrect.