

Internal Field Action Root-Cause Note

Topic	Internal note
Root cause	ASIC comparator drift observed in engineering pilot bench test.
Legal hold	GT-300 LOT-2199X remains attorney work product and must not be published.
Public explanation	Use customer-safe language: potential sensor reading shift under specific storage conditions.
Retain internally	FA-INT-07 and FA-LEGAL-08 remain in the reconciliation workbook only.