Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: ak63hse Make: Mercedes

Model: 207.302 - E 220 CDI BlueEFFICIENCY Coupe

Year:

VIN: WDD2073022F252006

Mileage: 40045km

Vehicle Software Version: V48.70

Diagnostic Application Version: V3.08.001

Test Time: 2017-08-03 09:48:34

Tester: russell emptage

Diagnostic path: Automatically Search



Diagnostic Result

(5)	
(1)	Abnormal
C10C800 System "COLLISION PREVENTION ASSIST" has triggered a warning.	STORED
(9)	Abnormal
B171315 Trunk/load compartment lamp 2 has a malfunction.There is a short circuit to positive or an open circuit.	STORED
B1FAD00 The left brake lamp has a malfunction.	STORED
B1FAE00 The right brake lamp has a malfunction.	STORED
B280215 The outer right stop lamp and taillamp has a malfunction. There is a short circuit to positive or an open circuit.	STORED
B280015 The left outer stop lamp and taillamp has a malfunction.There is a short circuit to positive or an open circuit.	STORED
B1FAF00 The left taillamp has a malfunction.	STORED
B1FB000 The right taillamp has a malfunction.	STORED
B280315 The inner right stop lamp and taillamp has a malfunction. There is a short circuit to positive or an open circuit.	STORED
	C10C800 System "COLLISION PREVENTION ASSIST" has triggered a warning. (9) B171315 Trunk/load compartment lamp 2 has a malfunction. There is a short circuit to positive or an open circuit. B1FAD00 The left brake lamp has a malfunction. B1FAE00 The right brake lamp has a malfunction. B280215 The outer right stop lamp and taillamp has a malfunction. There is a short circuit to positive or an open circuit. B280015 The left outer stop lamp and taillamp has a malfunction. There is a short circuit to positive or an open circuit. B1FAF00 The left taillamp has a malfunction. B1FB000 The right taillamp has a malfunction. B280315 The inner right stop lamp and taillamp has a malfunction. There is a short circuit to positive or an open

	B280115 The left inner stop lamp and taillamp has a malfunction.There is a short circuit to positive or an open circuit.	STORED
PTS - PARKTRONIC(N62)	(1)	Abnormal
	U016887 Communication with the electronic ignition lock has a malfunction. The message is missing.	STORED
ZAN - Audio/COMAND display(A40/8)	(1)	Abnormal
	c155 Communication with the instrument cluster has a malfunction.	STORED
DCU_LF - Left front door(N69/1)	(1)	Abnormal
	990915 The output for actuator motor 'Additional door lock' has a malfunction. There is a short circuit to positive or an open circuit.	Stored
Normal	(18)	
ECM - Engine Control Module(CDID2/CDID3) for combustion engine 'OM651'(N3/9)		Normal
TCM - Transmission Control Module		Normal
FSCU - Control unit'Fuel pump'(N118)		Normal
ESP - Electronic stability program(N30/4) CGW[ZGW] - Central		Normal Normal
gateway(CGW[ZGW]) Driver-side SAM - Front		Normal
signal acquisition and actuation module(N10/1)		Nominal
EZS - Electronic ignition lock(N73)		Normal
XALWA_L - Left xenon headlamp(E1n1)		Normal
XALWA_R - Right xenon headlamp(E2n1)		Normal
SRS - Supplemental restraint system(N2/10)		Normal
RevETR_LF - Left front reversible emergency tensioning retractor(A76)		Normal
RevETR_RF - Right front reversible emergency tensioning retractor(A76/1)		Normal
SG_FOND - Rear control unit(N22/6)		Normal
IC - Instrument cluster(A1)		Normal
SCCM - Steering column module(N80)		Normal
ZBE - Audio/COMAND operating unit(A40/9)		Normal
DCU_RF - Right front door(N69/2)		Normal

Normal