## Vehicle diagnostic report

Shop Name: Address: Telephone: Email: Fax:

License #: abc1 Make: DEMO Model:

Year:

VIN: 1E4GEAK12FT00001X Mileage: 35565 (km)

Vehicle Software Version: V14.80

Diagnostic Application Version: 3.07.010

Test Time: 2017-05-17 13:20:18 Diagnostic path: Health Report



Diagnostic Result

| Fault   | (8)   |                              |
|---|---|------------------------------|
| ECM(Engine Control<br>Module)                       | (4)   | Abnormal                     |
|   | P0303 Misfiring of Cylinder 3(P0303) P2097 Throttle Valve Block(Ice up) P0401 EGR Valve A Flow Insufficient Detected P0174 System A/F Ratio too Lean (Bank 2)   |                              |
| TCM(Transmission<br>Control Module)                 | (3)   | Abnormal                     |
|   | P2500 The Transmission Has an Impermissible Transmission Ratio. P2502 The Gear is Implausible or the Transmission is Slipping. P2211 The Selector Lever is in an Intermediate Position.   |                              |
| ABS(Anti-lock Braking System)                       | (2)   | Abnormal                     |
|   | C1141 Brake Pressure Sensor B34<br>C1201 A7/7s1(BAS Release Switch) : Electrical Fault  |                              |
| SRS(Supplemental<br>Inflatable Restraint<br>System) | (3)   | Abnormal                     |
|   | B1878 Airbag-OFF-Lampe Fehlerart B1868 The Coding for the Ignition Circuit with Component R12/22(Left Rear Window Airbag Ignition Squib) is Faulty. B1019 The Ignition Circuit with Component R12/11(Left Rear Side Airbag Ignition Squib) Has Short Circuit to Positive. | Current<br>Current<br>Stored |

| BCM(Body Control<br>Module)              | (3)   | Abnormal |
|--|---|----------|
|  | B2277 Detecting Vehicle Submersion                                    |          |
|  | B2282 Vehicle Speed Signal B2323 RR-Door Motor ECU Communication Stop |          |
| IMM(Immobilizer)                         | (3)   | Abnormal |
|  | B2775 Interior Verification (to Theft Deterrent ECU / Smart Key ECU ) |          |
|  | B2776 Steering Lock Motor   |          |
|  | B2795 Unmatched Key Code  |          |
| TPMS(Tire Pressure<br>Monitoring System) | (2)   | Abnormal |
|  | C1501 Tire Pressure Sensor 1 Internal                                 |          |
|  | C1502 Tire Pressure Sensor 2 Internal                                 |          |
| SAS(Steering Angle<br>System)            | (3)   | Abnormal |
|  | C1630 SAS Timeout   |          |
|  | C2205 SAS Internal Error  |          |
|  | C121A SAS Initialization  |          |
| Normal                                   | (1)   |          |
| BMS(Battery Manager<br>System)           |   | Normal   |