

Event Causal Analysis – ECA-2026-0007

Related CR: CR-2026-00123 | Related WO: WO-2026-04567 | Governing SOP: SOP-AFW-001

Analysis Summary

Primary cause identified as mechanical misalignment corrected via WO-2026-04567.

[FIGURE PLACEHOLDER]

Figure 1: Cause-and-Effect Diagram for AFW Pump P-101A Event