

Condition Report – CR-2026-00123

Related SOP: SOP-AFW-001 | Related WO: WO-2026-04567 | Related ECA: ECA-2026-0007

Condition Description

AFW Pump P-101A experienced vibration alarm VB-101A at 6.2 mils.

[FIGURE PLACEHOLDER]

Figure 1: Vibration Trend for VB-101A During Surveillance Start