## Lab 7 - Student Work Distribution

- Isaac E.
  - Tried to debug the code in regards to the FIFO's and UART communication
  - Don't think I did much in that regard as the project still does not work correctly
- Jacob S.
  - Attempted to rework the FIFO and UART RX module in order to account for two FIFOs with buttons for pulling into barrel shifters
  - Cleaned up wiring in top module in order to work with new UART, wrote constraint and tried to debug demo
- Adrian A.
  - Assisted with Top\_File and constraint.