Garment Defect Classification Chart

Department: Quality Assurance
Based on BKMEA Quality Control Standard

Critical Defects (Zero Tolerance):

- Needle breakage in garment
- Sharp object in garment
- Wrong size label on export carton

Major Defects (AQL < 2.5%):

- Broken stitch
- Open seam
- Uneven stitch density
- Needle mark on fabric
- Color bleeding

Minor Defects (AQL < 4.0%):

- Loose thread
- Minor stain
- Uneven hem

Inspection Action:

- Major/Critical: Tag as defective, move to rejection bin, notify supervisor.
- Minor: Record and send for repair.