## PROBLEM[\$YMPTOMS[TABLE

DI8NI-01

Symptom	Suspect[Area	See[page
Audio system can not be controlled by pad switch.	Pad switch Power source circuit Steering pad switch Audio system	DI-975 DI-977 IN-35
LEXUS navigation system does not operate.	Pad switch Power source circuit Steering pad switch LEXUS navigation system	DI-975 DI-977 DI-1 <u>5</u> 98
Multi information display does not operate.	Pad switch Power source circuit Steering pad switch Combination meter system	DI-975 DI-977 DI-930
Cellular mobile telephone system can not be controlled by pad switch.	Pad switch Power source circuit Cellular phone communication circuit See dealer option repair manual	DI-975 DI-979 -