



STM Exercise 9


Phase Diagrams (Fe-C)

Sara Ferraris
sara.ferraris@polito.it



IRON-CARBON (Fe-C) PHASE DIAGRAM

- 2 important points

-Eutectic (A):





-Eutectoid (B):




120 μm


Result: Pearlite = alternating layers of α and Fe_3C phases.







Exercise 2: Determine the phase/s present their compositions and relative amount in points A, B, C (at the beginning of the peritectic transformation), D(at the end of the peritectic transformation), E and F for a steel with 0.34%C.



Exercise 3: Determine the phase/s present their compositions and relative amount in points A, B, C (at the beginning of the peritectic transformation), D(at the end of the peritectic transformation), E and F for a steel with 0.13%C.