

INC-2018-02: P-101 seal spray - minor CW release

Incident / Near-Miss Report: INC-2018-02 Category: loss_of_containment

Date: 2018-06-30 Area: Area 1 Equipment: P-101

Title: P-101 seal spray - minor CW release

NARRATIVE:

Mechanical seal on P-101 opened during monsoon start-up, spraying cooling water over the pump bay. No injury. First recorded instance of the monsoon seal distress pattern later seen in 2019/2021/2023/2024/2025 work orders.

ROOT CAUSE: Cavitation after strainer blinding (post-event analysis 2023).

PRECURSOR CONDITIONS: monsoon onset; STR-101 high dP; pump start after standby

CORRECTIVE ACTIONS: Initially treated as one-off; pattern recognized only in 2023.

Reported to: M. Pillai (Safety Officer)