

INC-2023-08: P-101 bearing distress following seal failure operation

Incident / Near-Miss Report: INC-2023-08 Category: equipment_damage

Date: 2023-07-23 Area: Area 1 Equipment: P-101

Title: P-101 bearing distress following seal failure operation

NARRATIVE:

Pump run briefly with failed seal (WO-2023-0771 event) allowed CW into bearing housing; DE bearing replaced. Consequential damage of the monsoon seal pattern.

ROOT CAUSE: Operation with failed seal; delayed changeover to P-102.

PRECURSOR CONDITIONS: seal leak alarm ignored for one shift; standby pump not started

CORRECTIVE ACTIONS: Changeover drill added; leak-off inspection on operator round.

Reported to: M. Pillai (Safety Officer)