

NM-2020-14: H2S odor at P-107 during seal replacement

Incident / Near-Miss Report: NM-2020-14 Category: near_miss_toxic_gas

Date: 2020-10-02 Area: Area 4 Equipment: P-107

Title: H2S odor at P-107 during seal replacement

NARRATIVE:

Fitters reported strong odor while breaking P-107 seal housing; area monitor peaked 4 ppm. Work paused, line flushed again, completed safely. Effluent service equipment retains H2S in dead legs.

ROOT CAUSE: Insufficient line flushing before maintenance on effluent service.

PRECURSOR CONDITIONS: effluent service equipment opening; incomplete flush

CORRECTIVE ACTIONS: Flush verification step added to effluent maintenance JSA.

Reported to: M. Pillai (Safety Officer)