

## NM-2021-11: Scaffold clamp dropped near V-205

Incident / Near-Miss Report: NM-2021-11      Category: near\_miss\_dropped\_object

Date: 2021-04-19      Area: Area 2      Equipment: V-205

Title: Scaffold clamp dropped near V-205

### NARRATIVE:

Clamp fell 6 m during scaffold erection, landing 2 m from a fitter.

ROOT CAUSE: Tool lanyard not used.

PRECURSOR CONDITIONS: work at height; loose tooling

CORRECTIVE ACTIONS: Tool tethering enforced.

Associated permit: PTW-2021-0233

Reported to: M. Pillai (Safety Officer)