

NM-2025-06: Exchanger bundle swing during extraction

Incident / Near-Miss Report: NM-2025-06 Category: near_miss_lifting

Date: 2025-02-27 Area: Area 1 Equipment: E-201

Title: Exchanger bundle swing during extraction

NARRATIVE:

E-201 bundle swung against structure during pull; rigging plan had not accounted for wind.

ROOT CAUSE: Rigging plan gap.

PRECURSOR CONDITIONS: heavy lift; wind above 20 km/h

CORRECTIVE ACTIONS: Wind limit added to lift plans.

Associated permit: PTW-2025-0119

Reported to: M. Pillai (Safety Officer)